

SURVEY & REMONUMENTATION

JAN 13 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

IRON COUNTY
MICHIGAN
RECEIVED FOR RECORD

97 DEC 23 PM 1:31
L.C. Records L.P. 170
Gilbert Stiles
REGISTER OF DEEDS

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>43N</u> R <u>34W</u>	<u>L.M-7</u>
	T _____ R _____	<u>001</u>
	T _____ R _____	
	T _____ R _____	
2. Property Controlling in Section	S _____ T _____ R _____	
	S _____ T _____ R _____	
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	
	S _____ T _____ R _____	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Meander Corner S.13 & S.24, T43N R34W

I, Gary L. Pisoni, in a field survey on March 21, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:
Original corner established by Guy H. Carleton, U.S. Deputy Surveyor on August 28, 1851.
Original corner: Wood Post
Original bearing trees:

Tamarack	8"	S 56° E	20 Links (13.20 feet)
White Birch	6"	N 29° E	17 Links (11.22 feet)

PEER GROUP APPROVED

Guy H. Carleton 12-19-97
IRON COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
No original corner evidence found.

Found a 1 1/4" diameter axle shaft, 5 feet from waters edge on East shore of Emily Lake marking corner position which has been used as a lot corner from an unrecorded plat for over 40 years. Accepted axle shaft as the best available evidence for restoring meander corner position.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set a 3/4" outside diameter by 3 feet long aluminum rod monument with a 3" dia. aluminum cap as a witness corner to axle shaft Meander Corner, stamped to read: T43N, R34W, W.C., M.C., S-13, S-24, 1997, RLS - 27457. Said monument is on line between axle shaft M.C. and the NE corner of Section 24.

From the above described axle shaft, I established the following new blazed and scribed bearing trees:
(All measurements taken to a nail in side of tree)

Red Maple	7"	N 24° E	17.34 feet
W.C.M.C.	1" x 3' Rod Mon.	S 87° 59'54" E	10.00 feet
Hemlock	15"	S 50° E	4.32 feet
Red Maple	20"	S 17° E	21.50 feet
Steel Sign Post	6'	S 87° 59'54" E	10.85 feet

37-17a

Signed by *Gary L. Pisoni*

Date December 16, 1997

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 27, 1997
REVISED MAY 14, 1975
REVISED JAN. 1983
REVISED OCT., 1995

