

SURVEY &  
REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron  
(County)

Located In:

Corner Code #

1. Public Land Survey T 43N R 35W H-11  
T     R          
T     R          
T     R
2. Property Controlling S     T     R      
in Section S     T     R
3. Miscellaneous S     T     R      
Property in Sec. S     T     R

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:07

L.C. Records 12.8, P. 278

*Gary L. Pisoni*  
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No.           , Recorded Plat             
5. Private Claims

Quarter Corner to Sections 27 and 34, T43N, R35W

I, Gary L. Pisoni, in a field survey on October 2, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on August 8, 1851 by Harvey Mellen, U.S. Deputy Surveyor.

Original Corner; Wood Post

Original Bearing Trees:

Sugar	6"	S 65° E	4 links (2.64 feet)
Sugar	12"	N 17° E	57 links (37.62 feet)

PEER GROUP APPROVED

*Gary L. Pisoni 11-30-2000*  
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

I set a P.K. nail in the centerline line of an East/West County Road and in line with a fence line running North.

I accept this position as the best available evidence for restoring the quarter corner.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set one reference monument being a 5/8" diameter by 30" long rebar pin with a 3" diameter aluminum cap stamped as follows:  
Iron County Remonumentation, T43N, R35W, R.M., 1/4, S-27, S-34, North, 25.82 feet, 2000, RLS 27457 from which I established the following new blazed and scribed bearing trees: (All measurements taken to a nail in side of tree)

Red Maple	5"	N 04°W	47.56 feet
Red Maple	9"	N 54°E	84.65 feet
Balsam	8"	S 44°E	73.17 feet
R.M.	5/8" x 30" rebar	South	25.82 feet
Steel sign post		South	26.5 feet

00-046

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISOR MAY 14, 1975  
No. 27457 REVISOR JAN. 1983  
REVISOR OCT. 1995

