

# SURVEY & REMONUMENTATION

FEB 21 2001

## SECTION

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

_____ Iron _____	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 43N R 36W	K-1 <input checked="" type="checkbox"/>
	T 44N R 36W	K-13
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, Robert A. Goodreau in a field survey on May 11, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

#### A. Description of original monument and accessories and/or subsequent restoration:

K-1/K-13 Original corner established by John Burt, U.S. Deputy Surveyor, in 1846.

Original witnesses: Yellow Birch 22" N 06° E 25 links  
Sugar Maple 14" N 79° W 64 links

Donald D. Lappala RLS replaced found local usage corner on 13 April 1967 w/ an 8" iron spike in centerline of old US 2. Distances to recovered quarter corners East and West check w/ original survey notes. He also set a 2" x 5' concrete filled reference monument w/ 3" bronze tablet at a point North, 23.13 ft. from Section corner (Liber 4, Page 52).

#### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-1/K-13 Found corner as described by Lappala.

Found reference monument as described by Lappala.

Found witnesses recorded by Lappala as:

Wisc. Mich. power pole #63-2784	North	24.3'	(36.8 links)
Wisc. Mich. power pole #66-1219	N 31° E	28.8'	(43.6 links)
Wisc. Mich. power pole #63-2728	S 29° E	34.7'	(52.6 links)
Reference monument	North	23.13'	

Corner record research on file with county representative.

#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-1/K-13 Accepted corner as found.

Witnesses:	Wisc. Mich. power pole #63-2784	North	24.44'	
	Wisc. Mich. power pole #66-1219	N 34° E	28.97'	
	Wisc. Mich. power pole #63-2728	S 29° E	34.62'	
	15" Spruce	S 60° W	56.55' (NBT)	
	Reference monument	North	23.13'	
	Reference monument (NEW, 5/8" iron pin w/ 3" aluminum cap)	S 34° E	38.87' w/ sign post	Sign Post 0.5' North

Note: Measurements taken to a nail in side of witnesses.

Signed by RA. Goh  
Surveyor's Michigan License No. 43053

Date July 1, 2000

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -5 PM 12:51

L.C. Record: L.S. P. 230

*Robert A. Goodreau*  
REGISTERED PROFESSIONAL SURVEYOR

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

PEER GROUP APPROVED

*Ken Layd* 11-14-2000  
COUNTY REPRESENTATIVE

