

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 14 T 44N R 31W S 14 T 44N R 31W S _____ T _____ R _____	J6 12
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on J6 05/09/13  
12 05/13/13 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(J6) Center of Section 14. Not previously monumented.

(12) South 1/16 corner, Section 14. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(J6) Established the position for the corner at the intersection of straight lines connecting  
opposite 1/4 corners.

(12) Established the position for the corner midway and on a straight line between Center of Section  
14 1313.95' north and Quarter corner 1313.95' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J6) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
15" Spruce N23°W 13.0' mrkd "C1/4 BT"  
7" Cherry S84°E 13.05' do  
5" Poplar S32°E 12.3' do  
5" Spruce S82°W 7.05' do  
Set sq'd cedar post adjacent.  
E=7911359.193 N=159259.028

(12) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
9" Maple N27°E 3.85' mrkd "1/16S BT"  
5" Balsam S47°E 8.65' do  
6" Maple S32°W 14.75' do  
4" Spruce N84°W 20.4' do  
Set sq'd cedar post adjacent.  
E=7911349.557 N=158858.718

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).  
Coord. Ref.=NGS PID RL0202: N= 156159.380 m. E= 7917031.363 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 05/15/2013

For the Michigan Department of Natural Resources, Forest Resources Division

