

SURVEY &
REMONUMENTATION

JAN 13 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

IRON COUNTY
MICHIGAN
RECEIVED FOR RECORD

97 DEC 23 PM 1:26

L.C. Records L-7 P.123

Gilbert Stiles
REGISTERED DEEDS

For corners in

Iron
(County)

Located In:

Corner Code #

1. Public Land Survey

T 44N R 32W

C-9

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

Section Corner Sec. 19, 20, 29, 30, T44N, R32W

I, Gary L. Pisoni, in a field survey on November 3, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established in July of 1849 by Zelotes B. Searls, U.S. Deputy Surveyor.

Original Corner; Cedar Post

Original Bearing Trees;

Fir	10"	S20° W	23 links (15.18 feet)
Cedar	20"	N70° E	17 links (11.22 feet)

On 8-6-84, Keith L. Sackett, RLS with the Michigan Dept. Of Natural Resources, restored the corner position from an original line tree South on top of ridge. Position checks with other corners in the area. Set a 1" x 32" iron pipe with a 4 inch diameter aluminum cap. Recorded in Land Corner Certificate L. 5, Page 75, on September 14th, 1984.

1984 Bearing Trees;

Cedar	16"	N08° W	25.6 feet
Cedar	12"	S62° E	26.7 feet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

On 11-3-97 found monument as set by Keith Sackett in 1984 along with the following bearing trees;

Cedar	16"	N08° W	26.04 feet
Cedar	13"	S66° E	27.40 feet

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

Black Ash	7"	S30° E	23.18 feet
Black Ash	6"	N46° W	27.18 feet
Steel Sign Post		N07° E	0.83 feet

PEER GROUP APPROVED

Gary L. Pisoni 11-11-97
IRON COUNTY REGISTERED LAND SURVEYOR

97-18

Signed by Gary L. Pisoni

Date November 7, 1997

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995