SURVEY &

Steel sign post

27457

97-28

Signed by

Surveyor's Michigan License No.

REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE JAN 1 3 1998 . IROH COUNTY Filing Requirement of Act 74, Mich. P.A. 1970 MICHIGAN RECEIVED FOR RECORD For corners in SECTION ron Located in: Corner Code # 97 DEC 23 PM 1: 27 L.C. Records 6.7 P. 133 1. Public Land Survey T_44N R_32W REGISTED OF REFDS 2. Property Controlling in Section T R 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number , Recorded Plat 4. Lot No. 5. Private Claims South Meander Corner between Section 16 and 17, T44N, R32W I, <u>Gary L. Pisoni</u>, in a field survey on <u>November 7</u>, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 4 in lines 1 and 2 above were in conformance with regulations and rules therefore as 6 required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 10 NOTE: Not more than 2 corners, all in the same town and range, may be recorded 11 on this certificate. 12 1: A. Description of original monument and accessories and/or subsequent restoration: Original corner established by Zelotes B. Searls, U.S. Deputy Surveyor, in July 1849. Original Corner: Cedar (Meander Corner) 8" Description of corner evidence found and/or method applied in restoring or reestablishing corner: No evidence of original B.T.s found. Found a 3/4" diameter iron pipe located on the South Edge of Light Lake as the Meander corner as shown on the Houlmont Unrecorded Plat of Gov't Lot 1, Section 17. PEER GROUP APPROVED Accepted the iron pipe as the best available evidence for restoring corner position. Corner record research on file with County Representative. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced 3/4" diameter iron pipe 3 1/2" long with a 3/4" outside diameter aluminum fod monument 36" long, 5" above ground surface with a 3" dia. aluminum cap stamped as follows: Iron County Remonumentation, T44N, R32W, M.C., S-17, S-16, 1997, RLS 27457 from which the following bear: (all measurements taken to a nail in side of tree, no scribing or signs on B.T.s) Red Maple 8" S 34°E 8.61 feet 8" Red Maple S 24°W 18.88 feet OF MICHIGA Red maple S 73°W 28.63 feet

South

Date .

1.0 feet

November 8, 1997

GARY E

PISONI LAND

SURVEYOR

SUPPRIEVERS SPED LANG Anna RED LAGRON