

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 35 T 44N R 32W S 35 T 44N R 32W S _____ T _____ R _____ S _____ T _____ R _____ S _____ T _____ R _____	J12 13 _____ _____ _____
3. Miscellaneous Property in Sec.	_____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

I, Stephan J. Szyszkoski, in a field survey on J12 04/28/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(J12) Center of Section 35. Not established in the original survey.

(13-Sec. 35) Southeast 1/16 corner, Section 35. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(J12) Established the corner at the intersection of straight lines connecting opposite 1/4 corners.
From the corner thus established, I found a 1/2" uncapped rebar, not of record, at the intersection
of newer blue painted lines to the west and the north, apparently used by others as an approximate
corner, N83E 20.6' distant, which I did not accept as marking the position for the corner.

(13-Sec. 35) Established the corner at the intersection of straight lines connecting opposite 1/16
corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J12) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Poplar S65E 1.9' mrkd "C1/4 BT"
9" Maple N70W 32.6' do
4" W.Spruce N58W 23.9' do
8" Maple N17W 19.45' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

(13) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
10" Sugar N60E 28.4' mrkd "1/16S BT"
4" Sugar S36E 17.0' do
11" Sugar S08W 12.8' do
6" Sugar in clump N37W 7.4' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 05/04/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division



16418

16419