

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>44</u> N. <u>X</u> S. R. <u>34</u> E. <u>X</u> W.	<u>I10 & J9</u>
2. PROPERTY CONTROLLING IN SECTION <u>23</u>	T. <u>44</u> N. <u>X</u> S. R. <u>34</u> E. <u>X</u> W.	<u>16b</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ S. R. _____ E. _____ W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER _____

Arthur O. Enger _____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner I10 ($\frac{1}{4}$ corner between Sections 26 & 27, T44N, R34W):

Wood post	(Not found. No subsequent monuments found.)
Y. Birch 20 N40W 5	(" " " " accessories ")
Sugar 6 S66E 11	(" " " " " ")

Corner J9 ($\frac{1}{4}$ corner between Sections 23 & 26, T44N, R34W):

Wood post	(Not found. No subsequent monuments found.)
Sugar 10 N30E 31	(" " " " accessories ")
Sugar 12 S40W 14	(" " " " " ")

Corner 16b (West Meander Corner between Sections 23 & 26, T44N, R34W):

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

No evidence of monuments or accessories, original or subsequent.

Corner I10: Re-established 7/11/77 on line between Sec. Corners 39.998 ch. to N and to S.

Corner J9: Re-established 7/12/77 on line between Sec. Corners 40.245 ch. to E and to W.

Corner 16b: Re-established 7/12/77 on true sec. line on W bank of Paint River, 11.947 ch. W of Sec. Cor. 23, 24, 25, & 26 and 27.621 ch. E of $\frac{1}{4}$ corner 23 & 26. There appears to have been a measurement error in the original survey measurement across the river, as the distances to

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Monuments for all three corners: 1" I.D.x36" iron pipe with 3 3/4" aluminum cap

Witnesses for Corner I10:	Sugar Maple 10 N12°E (mag.) 30.7 ft. " $\frac{1}{4}$ S, NBT"
Declination 0°15' East	Sugar Maple 10 N85°W (mag.) 29.6 ft. " $\frac{1}{4}$ S, NBT"
Witnesses for Corner J9:	Sugar Maple 11 N45°E (mag.) 12.4 ft. " $\frac{1}{4}$ S, NBT"
Declination 0°05' West	Sugar Maple 6 S82°W (mag.) 3.0 ft. " $\frac{1}{4}$ S, NBT"
Witnesses for Corner 16b:	Sugar Maple 14 N28°W (mag.) 46.6 ft. "MC, NBT"
Declination 0°50' West	Black Ash 11 S22°W (mag.) 22.5 ft. "MC, NBT"

SIGNED BY _____ DATE July 28, 1977

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE July 28, 1977

MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581