

# SURVEY & REMONUMENTATION

FEB 21 2001

## SECTION

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Iron</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>44N</u> R <u>34W</u>	<u>A.B-3</u> <u>(003)</u>
	T <u>    </u> R <u>    </u>	
	T <u>    </u> R <u>    </u>	
	T <u>    </u> R <u>    </u>	
2. Property Controlling in Section	S <u>    </u> T <u>    </u> R <u>    </u>	
	S <u>    </u> T <u>    </u> R <u>    </u>	
3. Miscellaneous Property in Sec.	S <u>    </u> T <u>    </u> R <u>    </u>	
	S <u>    </u> T <u>    </u> R <u>    </u>	

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:03

L.C. Records: L.8, P. 254

*Gary L. Pisoni*  
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No.         , Recorded Plat           
5. Private Claims         

East Meander Corner between Sections 6 and 7, T44N, R34W on East bank of Paint River.

I, Gary L. Pisoni, in a field survey on April 4, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

#### A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on August 18, 1851 by Guy H. Carleton, U.S. Deputy Surveyor

Original Corner; Wood Post

Original Bearing Trees:

White Pine	12"	N 38° E	35 links (23.10 feet)
Cedar	6"	S 50° E	6 links (3.96 feet)

On 8/25/76, Arthur O. Enger restored the meander corner position at record bearing and distance from the stump remains of the original white pine bearing tree and set a 1" diameter by 36" long iron pipe with a 3 3/4" diameter aluminum cap stamped as follows: T44N, R34W, M.C., S-6, S-7, 8/25/76, RLS 13581, recorded in Liber 1, Page 519 of LC records.

1976 Bearing Trees:

White Spruce	8"	S 53° E	39.5 feet
White Spruce	13"	N 14° W	12.0 feet

#### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found evidence of white pine bearing tree stump.

On 4/4/2000 found the above describe monument and the following bearing trees:

White Spruce	15"	N 15° W	12.40 feet
White Spruce	12"	S 56° E	39.96 feet

PEER GROUP APPROVED

*Don Ray L. Pisoni 11-30-2000*

COUNTY REPRESENTATIVE

Monument is 10" above ground and 21 feet from waters edge.

Corner record research on file with County Representative.

#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

Balsam	8"	N 49° E	35.78 feet
Spruce	5"	S 78° E	15.28 feet
Steel sign post		East	0.85 feet

00-022

Signed by

*Gary L. Pisoni*

Date

11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971