

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

_____ Iron _____ Located In: _____ Corner Code # _____
(County)

1. Public Land Survey T 43N R 36W E-1
T 44N R 36W E-13
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Robert A. Goodreau in a field survey on May 10, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
E-1/E-13 Original corner established by Austin Burt, U.S. Deputy Surveyor, in 1847.

Original witnesses: Yellow Birch 10" N 64° E 38 links
Yellow Birch 14" N 32° W 40 links
Hemlock 10" S 30° W 19 links
Hemlock 18" S 40° E 18 links

Donald D. Lappala RLS restored corner position on 9 September 1964 w/ a chiseled (x) in pavement, using 1934 Michigan State Highway project plans and 2 reference monuments. He also set a 2" x 5' concrete filled reference monument w/ bronze tablet (Liber 3, Page 287).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-1/E-13 Found RR spike in monument box set by unknown surveyor.

Found reference monument set by Lappala described as: South 34.85'

Found witness recorded by Lappala as: 14' Elm N 40° W 91.7' (138.9 links)

Corner record research on file with county representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-1/E-13 Accepted corner as found.

Witnesses: 17" Elm stub N 34° W 91.41'
6" Hemlock S 34° E 64.10' (NBT)
7" Maple N 30° E 94.67' (NBT)
Ref. mon. South 34.85'
Sign post 1' South of reference monument

Note: Measurements taken to a nail in side of witnesses.

Signed by R.A. Good
Surveyor's Michigan License No. 43053

Date July 1, 2000

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -5 PM 12: 50

L.C. Records: L.S., P. 224

Robert A. Goodreau
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

PEER GROUP APPROVED

Don D. Lappala 11-14-2000
COUNTY REPRESENTATIVE

