## STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

## LAND CORNER RECORD

	<u> </u>
	T 45N R 30-31W
DESCRIPTION OF CORNER	Section Corner 1, 6, 7, and 12
CORNER MONUMENT	l" I.D. x 36" iron pipe with 4" aluminum cap
DATE MONUMENT PLACED ANI	D WITNESSED April 30, 1969
WITNESSES TO CORNER	B. Spruce 6 S59°W 11 1ks. "\$12 NBT"
N	B. Spruce 6 S72°E 15½ 1ks. "S 7 NBT"
	B. Spruce 8 N21°E 40 lks. "S 6 NBT"
	AND B. Spruce 5 N31°W 18½ 1ks. "S 1 NBT"
CIRCLE CORNER REGISTE	RED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Monument placed by proportionate measurement on line between Section Corner 80.07 chains south and Township Corner 81.923 chains north. Found no evidence of original corner or its accessories or of any replacement monument or accessories, and no reliable land ties are nearby.

Variation at this corner is about 2015 West.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing