

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: 04/26/2016

For corner(s) in: Iron County

Original Public Land Survey Corner

Corner Code

b. S T 45N R 31W K05 (GCDB 600500)
 S T R
 S T R
 S T R

Property Corner

1/16 Corner Code

a. S 13 T 45N R 31W 3 (GCDB 600460)
 a. S 14 T 45N R 31W 7 (GCDB 600460)
 S T R
 S T R

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13	A	B	C	D	E	F	G	H	I	J	K	L	M	13

Part A. Corner History

a.) North 1/16 corner between Sections 13 and 14. Found no record of monumentation.

b.) Corner common to Sections 11-12-13-14. 1980 - Reestablished recorded by A.O.Enger RLS. Set 1"IDx36" iron pipe with 3-3/4" aluminum cap. Red Maple 5" N7-1/2°W 24.4', Cherry 8" S89-1/2°W 47.6', Declination noted as 11°25'West.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) Found a 1"ID iron pipe with 3-1/2" aluminum MI Dept. of Natural Resources cap, stamped "N1/16 14|13 K.L.Sackett RLS 19006 8/5/1980", not of record. The monument is substantially midway and on a straight line between corners K5 and K6 and I accept same as a careful and faithful establishment of the position of the corner.

b.) Found the 1980 monument in good condition and at record bearing and distance from the 1980 Red Maple NBT, in good condition, now 10" with overgrown blazes. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

(a.) Found 1"ID I.pipe with 3-1/2" alum. MDNR cap.
 Set measuring nail with MDNR tag in the side of:
 7" Spruce N13°E 16.9' mrkd "1/16S BT"
 5" Spruce N61°E 7.35' do
 10" Spruce S02°W 15.1' do
 5" Spruce West 12.55' do
 Existing sq'd cedar post adjacent.
 E= 7912336.594 N= 169240.836

b.) Found 1"ID I.pipe with 3-3/4" alum. MDNR cap.
 10" Maple N01°W 24.75' old blazes (1980 NBT)
 6" Poplar S18°E 20.85' mrkd "S13 NBT"
 9" W.Birch S64°W 20.8' "S14 NBT"
 9" Poplar N64°W 29.7' "S11 NBT"
 Existing sq'd cedar post found adjacent.
 E= 7912344.838 N= 169652.790

Bearings are magnetic. Coordinates are MCS83, NAD83(2011) Epoch 2010.00, in meters.
 Coordinate Reference: NGS PID RL0202, E= 7917031.357 m. N= 156159.387 m.

Stephan J. Szyszkoski

08/23/2016

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908

