

SURVEY &
REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron Located In: Corner Code #
(County)

1. Public Land Survey T. 45N R. 34W B-11
T. R.
T. R.
T. R.

2. Property Controlling S. T. R.
in Section S. T. R.

3. Miscellaneous S. T. R.
Property in Sec. S. T. R.

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:01

L.P. Regals: L. S. P. 246

Robert J. Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

Quarter Corner to Sections 30 and 31, T45N, R34W

I, Garv L. Pisoni, in a field survey on April 3, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established in July 1851 by Guy H. Carleton, U.S. Deputy Surveyor

Original Corner; Wood Post

Original Bearing Trees:

Yellow Birch 10" S 25° E 36 links (23.76 feet)
Spruce 10" N 14° E 64 links (42.24 feet)

On 1/22/74, Arthur O. Enger RLS DNR restored the quarter corner position by proportionate measurement and set a 1" diameter by 36" long iron pipe with a 4" diameter aluminum cap stamped as follows: T45N, R34W, 1/4, S-30, S-31, 1/22/74, RLS 13581, recorded in Liber 1, Page 371-372 of LC records.

1974 Bearing Trees:

White Spruce 12" N 22 1/2° W 29.3 feet
White Spruce 7" S 06° W 23.5 feet

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

On 4/3/2000 found the above described monument and the following bearing trees:

Spruce 13" N 21° W 30.04 feet
Spruce 9" S 08° W 23.56 feet

Monument is 12" above ground surface.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

Popple 9" S 31° E 31.90 feet
Red Maple 11" West 38.96 feet
Steel sign post N 45° E 0.8 feet

00-014

Signed by Garv L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

