

# SURVEY & REMONUMENTATION

FEB 21 2001

## SECTION

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Iron</u>	Located In:	Corner Code #
(County)		
1. Public Land Survey	T <u>45N</u> R <u>34W</u>	<u>C-12</u>
	T <u>    </u> R <u>    </u>	<u>    </u>
	T <u>    </u> R <u>    </u>	<u>    </u>
	T <u>    </u> R <u>    </u>	<u>    </u>
2. Property Controlling	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>
in Section	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>
3. Miscellaneous	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>
Property in Sec.	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:01

L.C. Records: L. S. P. 247

*Gailend Pisoni*  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No.     , Recorded Plat       
5. Private Claims     

Quarter Corner to Sections 31 and 32, T45N, R34W

I, Gary L. Pisoni, in a field survey on April 3, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established in July 1851 by Guy H. Carleton, U.S. Deputy Surveyor.

Original Corner; Wood Post

Original Bearing Trees:

Fir	10"	West	4 links (2.64 feet)
Spruce	12"	N 30° E	9 links (5.94)

On 11/23/73 Arthur O. Enger RLS DNR restored the quarter corner position by proportionate measurement and set a 1" diameter by 36" long iron pipe with a 4" diameter aluminum cap stamped as follows: T45N, R34W, 1/4, S-31, S-32  
Recorded in Liber 1, Page 371-372 of LC records.

1973 Bearing Trees:

White Pine	36"	N 34 1/2° W	62.4 feet
White Birch	8"	N 20 1/2° E	123.9 feet

PEER GROUP APPROVED

*Gary L. Pisoni 11-30-2000*  
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

On 4/3/2000 found the above described monument and the following bearing trees:

White Pine	36"	N 38° W	62.95 feet
White Birch	11"(dbl)	N 20° E	124.20 feet
Wood Post	3"x3"	N 05° E	1.5 feet

Monument is 16" above ground surface and located approximately 40 feet North of creek.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

Balsam	6"	N 11° W	49.81 feet
Tamarack	5"	N 28° E	66.00 feet
Steel sign post		N 32° W	1.8 feet

00-015

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 26, 1971  
REVISED MAY 1990  
REVISED JAN. 1983  
REVISED OCT. 1995

