

LAND CORNER RECORDATION CERTIFICATE
MAY 28 1997
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970
COMMISSION

FOR CORNERS OF --:	LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 46N N. 37W E. S., R. W.	G3
2. PROPERTY CONTROLLING IN SECTION _____	T. _____ N. S., R. W.	
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. S., R. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

IRON COUNTY
MICHIGAN
RECEIVED FOR RECORD
96 DEC 10 PM 3:34
L.C. Records & P.18
District of Deeds
REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Patrick R. Leemon do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on August 15, 1996, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Section Corner common to sections 3, 4, 9 and 10 of T46N R37W

1851 survey by Elias C. Martin Set Y. Birch Post, (1) Hemlock 12 S85E 16 links, (2) Hemlock 16 N84W 27 links
1972 survey by Donald D. Lappala #12585 Set 2.5"x60" I.P. w/brass cap from wit's. 1 and 2,
(3) S. Maple 5 N36E 14.1 ft., (4) S. Maple 9 S32E 23.8 ft., (5) S. Maple 6 S81W 22.0 ft.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I found the 2.5"x60" Iron Pipe filled with concrete w/brass cap by Lappala in good condition. Witnesses 1 and 2 are gone. Witness 3 and 5 are in good condition. Witness 4 is a stump. Lappala filed a corner certificate in the Iron County Court House. This monument is accepted as a careful and faithful perpetuation of the position of the original corner.

County Research and Field Search information is on file with the County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Section Corner common to sections 3, 4, 9 and 10 of T46N R37W

Monu. The 2.5"x60" Iron Pipe filled with concrete w/brass cap was left in place.

Witnesses:

60d spike in the east side of a R. Maple 11 N4E 18.38 ft.

60d spike in the northeast side of a R. Maple 15 N48W 24.14 ft.

S. Maple 7 N38E 14.20 ft.

S. Maple 10 S82W 21.98 ft.

W1/4 3 N 0-56-56 W 2627.56 ft.

S1/4 3 S89-21-52E 2657.56 ft.

SIGNED BY Patrick R. Leemon DATE August 15, 1996

SURVEYOR'S MICHIGAN REGISTRATION NO. 31595

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

