JACKSON COUMTY TOROVED LAND CORNELL						APR 0 7 1998					
Northeast Corner of Section 24, Henrietta Township  LAND CORNER RECORDATION CERTIFICATE  Filing Requirement of Act 74, Mich. P.A. 1970					SECTION #2056335						
For corners in  JACKSON Located in: Corner Code #  (County)		Liber :5 <b>57 Page 11</b> Page 1 - of 1 Jackson Co., MI Recorded									
1. Public Land Survey  T1S R1E M-7  T R T R  T R				12/18/1997 <b>02:04P</b> Mindy Reilly Register of Deeds							
2. Property Controlling       S T R	Reg	iste	r of De	eds S	-	% File I					
4. Lot No, Recorded Plat  5. Private Claims		1 /	4 B (	C D	DEFGHIJKLM						
	<del></del>	2	<b>6</b>	5	4	3	2	- ] -			
I, David E. Erickson, in a field survey on June 5 , 19 97,		3	7	8	. 9	10	11	12			
Court of Law; established, re-established monumented, re-monumented, recovered, found as			18	17	16	- 15	14	13			
			19	20	21	22	23	24			
expressed below:  NOTE: Not more than 4 corners, all in the same town and range, may be recorded		9 10	30	29	28	27	26	25			
on this certificate.  A. Description of original monument and accessories and/or subsequent restorations.	ion <sup>.</sup>	11 12 13	31	32	33	34	-35	<b>3</b> 6			
In 1825, J. Wampler - Deputy Surveyor, set a "Post" and lists two witnesses: "Tamarack 7, S35°W, 93" (61.38') and "do 10, S80°W, 110 1/2" (72.93').											
In 1888, H.F. Bean, stated "Post gone. One witness for this post are standing & one witness for post 5 links South" and lists two witnesses: "W. Oak 12, N8°E, 242" (159.72') and "Willow 10, N89 1/2°E, 13 1/2" (8.91').											
In 1980, T.B. VanGieson - LS #24621, reports the corner as "Fireclay."  Oak N10°E 160.07', #60 nail in 10" Willow N40°E 154.26', #60 nail in popole N40°W 71.27' "per Certificate of Survey (C.O.S.) Job No. 80-55 and	and list	s fo	ur wi 55°W	tness 58.91	es: "#	60 na	il in 3				
A Jackson County Road Commission (JCRC) corner index card indicat	es the sa	ame	witne	esses	as Va	nGies	on.				
In 1994, A.L. Scheppelman - LS #35998, recorded the corner as "3/4" pipe (cap #24621) 4' South of centerline "X" roads N-S-W". and recorded four witnesses: "1/2" rerod (cap #28409) South 3.30' (A-7, T1S, R2E); 40d nail in W. side 48" Oak 160.0'; nail & tag in NE side power pole N50°W 70.58'; nail & tag in SE side power pole S 65° W 58.69' " per Land Corner Recordation Certificate (LCRC) recorded in Liber 4, Page 267.											
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:											
Found monument box with 1" x 24" iron pipe. Found 10" long midd section, 1.5' deep and 0.15' South of pipe. Accepted found Fire Clay as position of the original corner. Removed middle section of FC and plower section of FC. Did not place pipe or FC piece in hole due to eplace.	s a carefu aced a s	ul a tan	nd fai dard l	ithful Harris	<u>perpe</u> on me	<u>tuatio</u> onume	n of tent ov	he er			
C. Description of monument for corner and accessories established to perpetuate	locating ti	ne p	osition	of the	corner	जिल्लासम्बद्धाः इ.स.च्या	Marke .				
Set standard Jackson County Harrison monument with cap stamped "#	29245".			A STANFARE	ATE.	L MIC	11/6/1	HALLE			
N 07° E Set nail and tag #29245, West side 40" Oak (Bean Witness South Harrison monument at A-7, T1S, R2E S 60° W Set nail and tag #29245, South side power pole N 47° W Set nail and tag #29245, Northeast side power pole S 83° E County Surveyor sign post		60.1 3.1 58.5 70.6 19.	9' 1' 2' 4' 6'	** ** LICK	D/ ER Land	AVID E. ICKSON I Survey No. 29245	SURVE	THE THE THE			
NOTE: Bearings are magnetic	~ ~				· PARTIE	vanns <sup>a</sup>	PPIN.				
Signed by Laud Cuch In Date 12-9	-97										
Surveyor's Michigan License No. 29245 FORM APPROVED BY MICHIGAN	N STATE BOARD	OF LA			28, 1971 R WORD P		D MAY 14, SED JAN., S MARCH,	983			