

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD

H-9 JACKSON COUNTY


T 25 R 16

DESCRIPTION OF CORNER S 1/4 CORNER SEC. 22

CORNER MONUMENT SPIKE IN PAVEMENT

DATE MONUMENT ~~REMOVED~~ AND WITNESSED 10/9/69

WITNESSES TO CORNER..... 20" W. OAK N24°45'W 52'



24" W. OAK S87°45'W 53.9'

SW CORNER GARAGE N75°E 53.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

WITNESSES FURNISHED BY CONSUMERS POWER 10/9/69

SURVEYOR'S SEAL

SIGNED

[Signature]
REGISTERED LAND SURVEYOR

DATE

Oct 69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68