

P.A. 344 of 1990

Chairman

Date MAY 15 1997

SURVEY & DOCUMENTATION

APR 07 1998

SECTION

For corners in

#2053270
Liber 1555 Page 76
Page 1 of 1
Jackson Co., MI
Recorded
11/14/1997 01:40P
Mindy Reilly
Register of Deeds

<u>Jackson</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>3S</u> R <u>2W</u>	<u>K-6</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Michael A. Groat, in a field survey on May 13, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

[illegible]

A. Description of original monument and accessories and/or subsequent restoration:

Original Survey by Lucius Lyon, 1885, Set post, W. Oak, 12", N38°W, 56 Lks; W. Oak, 11", S6°E, 27 Lks.

H.F. Bean, 1886, Found stone and both witnesses. Hick, 14", S77°E, 147-3/4 Lks; Hickory, 20", S8-1/2°W, 333 Links

Consumers Power Company Witnesses from 1953: Iron in Monument Box, 12' East of West edge of pavement. NW corner of stone corner post, S45°E, 44.4'; 10" Cottonwood, West, 31.0'; 8" Walnut, S45°W, 34.1'; C.P. Pole, N40°E, 51.55'; 12" Walnut, S40°W, 34.25'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a monument box in the centerline of road with a 3/4" pipe inside. 1' down found bits of fireclay and at 2' found bottom half of fireclay. Under fireclay, found a large rock. Accepted the position of the fireclay as a careful and faithful perpetuation of the original corner. Set a 4"x36" concrete monument in place of the tile.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

The corner is a standard Jackson County concrete monument in a monument box with corner code and Township information stamped in the cap.

Witnesses:

N40°E	Nail and tag in Southerly side of utility pole	51.8'
S50°W	Nail and tag in Southerly side of 12" Walnut	34.10'
S30°E	Nail and tag in Southwesterly side of utility pole	62.50'
S60°W	Nail and tag in Southerly side of 10" Walnut	51.30'
N70°W	Survey marker sign post	31.10'

Signed by W. H. D. D.
Surveyor's Michigan License No. 39079

Date _____



Record 308