

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

**SURVEY &
REMONUMENTATION**

FEB 26 2001

SECTION

KALKASKA Located In: Corner Code #
 (County)
 2000 REMONUMENTATION
 1. Public Land Survey T 25N R 5W H-9
 T R
 T R
 T R
 2. Property Controlling S T R
 in Section S T R
 3. Miscellaneous S T R
 Property in Sec. S T R
 4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

I, EUGENE FARRIER, in a field survey on August 9, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H-9: 1/4 Cor. Common to Secs. 22 & 27, T25N-R5W, Garfield Township

July 29, 1852 GLO Resurvey by George H. Cannon, set post for corner; Sp. Pine 12" S 40° W 18 links; Sp. Pine 6" N 35° E 23 links.

May 5, 1981 Survey by Eugene D. Farrier set 1/2" Iron and Cap. S. P. In centerline Fletcher Road; N 19° E, 98.20', 8" Tw. R. Pine; S 41° E, 88.74', 12" R. Pine; S 56° W, 58.60', 7" R. Pine.

May 7, 1981 LCRC Eugene D. Farrier Liber 2 Page 307 set 1/2" Iron and Cap. S. P. In centerline Fletcher Road; N 19° E, 98.20', 8" Tw. R. Pine; S 41° E, 88.74', 12" R. Pine; S 56° W, 58.60', 7" R. Pine.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-9: 1/4 Cor. Common to Secs. 22 & 27, T25N-R5W, Garfield Township

Found Iron and Cap recorded in LCRC Eugene D. Farrier Liber 2 Page 307, in centerline E-W road; N 19° E, 98.20', found nail in 12" R. Pine; S 41° E, 88.74' found nail in 16" R. Pine.
 No G.L.O. witnesses were found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-9: 1/4 Cor. Common to Secs. 22 & 27, T25N-R5W, Garfield Township

Found Iron and Cap recorded in LCRC Eugene D. Farrier Liber 2 Page 307, in centerline E-W road; added 5/8" iron with brass cap in mon box.

N 23° W, 54.18' set nail and washer in J. Pine

N 19° E, 98.20' nail in 12" R. Pine found

S 41° E, 88.74' nail in 16" R. Pine found

S 38° W, 89.15' nail in 18" R. Pine found

Kalkaska County Peer Group accepted the above monument as a careful and faithful reestablishment of the position of the original corner.

Ratified by Peer Group

P.A. 345 - 1990 Kalkaska County

Chairman Eugene Farrier

Date 2-14-01

Signed by Eugene Farrier

Surveyor's Michigan License No. 24594

Date 2-15-01



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
 REVISED MAY 14, 1976
 REVISED JAN., 1983
 REVISED OCT., 1995



3026811

Page: 1 of 1

02/16/2001 10:25A

RENON

LB: 6 PG: 140

Kalkaska County Joan Hall, Register