

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

KALKASKA

(County)

Located In

Corner Code #

| | | | | | |
|--------------------------------------|---|-----|---|----|-----|
| 1. Public Land Survey | T | 25N | R | 6W | E-4 |
| | T | | R | | |
| 2. Property Controlling in Section | S | T | | R | |
| | S | T | | R | |
| 3. Miscellaneous Property in Section | S | T | | R | |
| | S | T | | R | |

4. Lot No: Recorded Plat:

5. Private Claims:

I, Craig W. McVean, in a field survey on Jan. 18, 2000 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

| | | | | | | | | | | | | |
|----|----|---|----|---|----|---|----|---|----|---|----|---|
| A | B | C | D | E | F | G | H | I | J | K | L | M |
| 1 | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | |
| 3 | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 5 | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | |
| 7 | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | |
| 9 | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | |
| 11 | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | |
| 13 | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

E-4 - GLO - Set 1/4 Post - G.H. Cannon - 1852

Cherry 12" N29°E 44 L.

W. Pine 24" S64°W 130 L.

- Fargo Eng. - 1912 - Fd. both U.S. Wit.

Set Iron pipe & crockery

W. Pine 28" N55°E 0.45, W. Pine Stp. S56°W 1.30 (US)

- M. Schaaf - 1941 - In stream intersect 1/4 corner 11 L. E.

of post. Fd. SW BT Stp. in place 20 L SW of stream. Corner

only 2 L. from W. Bank of stream. Tipped out WPS 28"

N22° W 64 L. to roots, WPS 10" N61°W 88 L., Cherry stp.

7" N75 1/2° W 16 L. Cherry Stp. 8" N 1/2°E 44 L.

- N.F. Parker - 1970 Survey - Placed 1/2" x 20" iron bar. 1"

pipe S80°E 11.3'

- LCRC L. 2, P. 11 - N.F. Parker - 1977 - 3/4" pipe & post

believed set by Fargo Eng. 1915. Placed 1/2" pipe

N89°45'W 28.4', 30 W. Pine N28°W 105.1', 1/2" bar North

221.0'

-LCRC L. 2, P. 138 - W.P. Richards - 1978 - Fargo Eng. Pipe found. A second corner was found and rejected which was a 1/2" iron rod lying N58°37'W 11.29' from Fargo iron.

- LCRC L.2, P. 243 - C.F. Roser - 1981 - Fd. old pointed 4" dia.

Post bottom, old pointed stake bottom and Fargo butter dishes - all buried in muck; also found Fargo BT Tipped Out, W. Pine Stp. 28" N55°E 29'. We fd. Fargo's 1" pipe (L. end had been straightened out) shoved in ground 0.4' SE of Parker's buried 1/2" rod. Parkers rod being N55°W 11.8' from True Fargo position. We placed a DNR Mon. cap on 1" x 36" pipe inside 1 1/4" x 48" pipe, all driven in muck & sq. cedar post at Fargo's position.

Set 5/8" x 36" rerod w/ RLS cap & cedar post N1°00'W 227.05'

Set 5/8" x 36" rerod w/ RLS cap & cedar post S89°31'E 29.00'

Set 5/8" x 36" rerod w/ RLS cap & cedar post S0°41'E 180.21'

Set 5/8" x 36" rerod w/ RLS cap & cedar post N89°33'W 36.00'

-Rec. Sur. - 2, P. 7, 9 & 10 - N.F. Parker - 1977

Same Wit as his LCRC.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

E-4 - 1/4 corner common to Sec. 8 & 9 - Fd. 4" DNR Alum. Cap on 1" iron pipe per Roser LCRC. Also found remains of SW GLO BT Stp. in place. Measure S. 58' +/- 3' (56'-GLO) to N'y Bank of Stream. DNR Mon. accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-4 - 4" DNR Alum. Cap on 1" Galv. Iron pipe.

SE 0.65' to face cedar post

Set Blue Carsonite post 1'N

East 29.05' to Fd. capped 5/8" Rebar on W'y bank of stream (CFR)

West 36.15' to Fd. capped 5/8" Rebar on E'y bank of stream (CFR)

S64°W 85.51' to set 1/2" x 9" Rebar in CL. remains 24" W. Pine Stp. (GLO)

N37°W 71.72' to N & T in W side 11" W. Pine scribed 'XBT'

N1°W 227.05' (R) to Fd. capped 5/8" Rebar (CFR)

S0°41'E 180.21' (R) to Fd. capped 5/8" Rebar (CFR)



Signed by:

Craig W. McVean

Date:

5/4/2000

Surveyor's Michigan License No.:

39088