



8 0 4 1 5 4 0
Tx:4028993

2/11/2015 4:45:00 PM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Kalkaska
(County)

Located In

Corner Code #

1. Public Land Survey	T	25N	R	7W	L12		
	T		R				
2. Property Controlling in Section	S	36	T	25N	R	7W	8
	S		T		R		
3. Miscellaneous Property in Section	S		T		R		
	S		T		R		

4. Lot No: Recorded Plat:

5. Private Claims:

I, Joshua R. Davidson, in a field survey on June 5, 2014 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5			4			3		2	1
3													
4	7		8			9		10		11		12	
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Register of Deeds Stamp & File Number

A. Description of original monument and accessories and/or subsequent restoration:

L12 – Center 1/4 corner section 36

8 – CW 1/16 corner section 36

None

None

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

L12 – Center 1/4 corner section 36

8 – CW 1/16 corner section 36

Set a stamped 2" aluminum cap on a 5/8" x 34" rebar per standard BLM procedure.

Set a stamped 2" aluminum cap on a 5/8" x 34" rebar per standard BLM procedure.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L12 – a stamped 2" aluminum cap on 5/8" x 34" rebar

8 – a stamped 2" aluminum cap on 5/8" x 34" rebar

N48°E 34.02' to set nail & tag in SE. side 8" R. Maple
S16°W 54.46' to set nail & tag in W. side 9" Cedar
S60°W 28.77' to set nail & tag in SE. side 10" Cedar
N54°W 21.52' to set nail & tag in SW. side 10" Cedar
Set blue post 1' Northeast

N48°E 46.78' to set nail & tag in NW. side 9" Cedar
S56°E 12.42' to set nail & tag in SW. side 17" Cedar
S14°E 22.64' to set nail & tag in W. side 13" Cedar
N50°W 48.14' to set nail & tag in SW. side 18" Cedar
Set blue post with location tag 1' Northwest.

Signed by:

Joshua R. Davidson

Surveyor's Michigan License No.:

46659

Date:

2-11-15

