

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

KALKASKA  
(County)

Located In:

Corner Code #

1999 REMONUMENTATION

1. Public Land Survey

T 25N R 7W

C-6

2. Property Controlling  
in Section

S

T

R

3. Miscellaneous  
Property in Sec.

S

T

R



Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, EUGENE FARRIER, in a field survey on November 17, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

C-6: 1/4 Cor. Common to Sec. 17 & 18, T25N-R7W, Garfield Township

1853, G.L.O. Resurvey, V.W. Caukin (Deputy Surveyor) Co. Survey Notes Pg 55, Hemlock 6" corner 1/4 sec., Ironwood 7", S76°E, 14 Lks; Sugar 6", N79.5°W, 42 Lks

1914, Survey, by W.S. Merrill (Co. Surveyor) Co. Survey Bk 34, Pgs 87-88, cedar stake in East wheel track in crossway one old Gov.B.T. stump, old witness stake on West side of road

1972, Survey & LCRC, by J.L. Wilcox, (LCRC recorded in Liber 1, Pg 12) set 1/2" iron in centerline of road & road fence South & prop. distances, 4' North of E-W fences, S85°W, corner fence post, 32.70'; N50°W, 9" Elm, 53.40'; S85°E, corner fence post, 33.43'

1997, Survey, by Farrier Surveying, found 1/2" iron 1' East of centerline of Henschell Road, West iron & cap #41098, 33'; set nail N40°W, fence post, 48.98'; set nail N40°E, 11" R. Pine, 74.23'; set nail N72°E, 10" R. Pine, 73.35'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-6: 1/4 Cor. Common to Sec. 17 & 18, T25N-R7W, Garfield Township

Found 1/2" iron & cap #14102 in centerline N-S road on fence to East & West.

N40°E, 74.23', 12" R. Pine, found nail

N72°E, 73.35', 10" R. Pine, found nail

West, 33.00', iron & cap #41098

N40°W, 48.98', fence post, found nail

No G.L.O. witnesses were found.

Ratified by Peer Group  
P.A. 345 - 1990 Kalkaska County

Chairman

Date 02-03-00



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-6: 1/4 Cor. Common to Sec. 17 & 18, T25N-R7W, Garfield Township

Found 1/2" iron & cap #14102 in centerline N-S road on fence to East & West. Pulled & set 5/8" X 18" rerod w/brass cap in mon. box.

N40°E, 74.23', 12" R. Pine, found nail

N72°E, 73.35', 10" R. Pine, found nail

West, 33.00', iron & cap #41098

N40°W, 48.98', fence post, found nail

Kalkaska County Peer Group accepted the above monument as a careful and faithful reestablishment of the position of the original corner.

Signed by Eugene Farrier  
Michigan License No. 24594

Date 02-04-00

Surveyor's