

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Kalkaska
(County)

Located In

Corner Code #

1. Public Land Survey T 26N R 5W K5
T R
2. Property Controlling in Section S T R
S T R
3. Miscellaneous Property in Section S T R
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Joshua R. Davidson, in a field survey on July 31, 2013 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

K5 – corner common to sections 11,12, 13 & 14, T26N, R5W

– 1852 – GLO Resurvey – G. Cannon – Set post Corner of sects. 11, 12, 13 & 14. –
1) SP. Pine 8" N30°E 16, 2) SP. Pine 8" S72°W 22.

– 1911 – County Survey Record Section 11 – No corner description.

– 1956 – DNR corner record – D. DeLaMater, PS #5778 – This corner was found by forestry division survey crew while making a partial resurvey of this township. Small slab of original BT stump in place. Corner checks with original corner to the East. – 1" pipe with 4" brass cap. – 3) 6" J. Pine S70°E 42½ links, 8) 7" J. Pine S84°W 69 links.

– 1978 – Consumer's Power Co. Survey drawing #S-F17406 – D. Ankrom, PS #21265 – No corner description.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

K5 – corner common to sections 11,12, 13 & 14, T26N, R5W

Found 4" Department of Conservation (DOC) brass cap monument on 1" iron pipe located inside the fenced in area of Camp Grayling. No GLO evidence was found. Based on measurements to the North and West, I believe the 4" DOC monument to be in the position used in the 1956 DNR survey. **Accepted found 4" DOC brass cap on 1" pipe as a careful and faithful perpetuation of the position of the original corner.**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K5 – Stamped 4" Department of Conservation brass cap on 1" iron pipe.

N62°E 5.46' to set nail & tag in NW. side 5" J. Pine
S22°W 86.94' to chiseled "X" on Easterly side of 2" aluminum fence post corner
N85°W 105.06' to set nail & tag in S. side 6" J. Pine
N03°W 44.19' to set nail & tag in W. side 4" J. Pine
Set Blue post 1' North.

Signed by:

Joshua R. Davidson

Date:

Dec. 16, 2014

Surveyor's Michigan License No.:

46659

