

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 26 NR. 6 W.

Kalkaska COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 23 and 24

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

36" W. Pine stump - S48W - 72 links

6" Maple - S26E - 48 1/2 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Forestry Division survey crew while making a resurvey of this township. Set corner by proportionate measurement between section corners. Corner falls about 2 links north of E-W fence and 32 links east of corner fence post. Could find no evidence to support the fence corner, which is about right for latitude but about 32 links out of line between section corners. Fences in this area do not lend themselves to any definite pattern of survey and must be given minimum consideration in corner restoration.

Corner was set and witnessed 10-19-59.

SURVEYORS SEAL

SIGNED *Kenneth J. Orloff*
REGISTERED LAND SURVEYOR

DATE 10/21/59