

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



# LAND CORNER RECORD

T. 27 N.R. 8 W


Kalkaska COUNTY

DESCRIPTION OF CORNER Sec. corner common to Sections 9-10-15-16

CORNER MONUMENT Set 1" pipe with 4" Aluminum cap

DATE MONUMENT PLACED AND WITNESSED 4-18-67

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

12" H. Maple S 75 E 39.8'

12" Hemlock S 40 W 36.4'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by double proportionate measurement between corners 1 mile West and 2 miles East, 1 mile South and 2 miles North. Nothing left for U.S. evidence or a previous corner. Checks U.S. record to physical features North and Merrill's 1/4 corner South.

SURVEYOR'S SEAL

SIGNED \_\_\_\_\_ DATE 4-25-67  
REGISTERED LAND SURVEYOR #10068