

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T...27 NR...8...W...

...Kalkaska... COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 14 & 15

DESCRIPTION OF CORNER MONUMENT 12 Pipe with 4" Brass cap

WITNESSES TO CORNER 9" Jack Pine - S 53 W - 121 Links

8" Jack Pine - S 36 E - 127 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

This corner had been previously located and perpetuated by Marcus Schaef,  
Registered Land Surveyor. Two original B.T.'s still in place, in poor condition.

Corner was placed and witnessed April 10, 1951.

SURVEYORS SEAL

SIGNED

Sean C. Seider  
REGISTERED LAND SURVEYOR

DATE 1/21/52