LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. PA 1970

			' '	ııı ıg	rtequii	Ciricin) / (OC 1 - 1, 1	VO. 1.	, , , , , ,	•						
For Corners In: Kalkaska (County)			Locate	d In		Corner	Code#									
1. Public Land Survey		T T	27N 28N	R	8W 8W	B1	3									
2. Property Controlling in Section	s	Т Т		R												
Miscellaneous Property in Section	s s	T T		R R						Regi	ster (of De	eds S	tamp	& File	Number
4. Lot No:	Recorde	d Pl	at:						Α Ε	3 C	D E	F	G H	ı J	K L	м
5. Private Claims:									2 -6		5	-	3-	2-		
I, <u>Craig W. McVean</u> , in a frequirements of PA 74, Mid and 2 above were in conform the current manual of sur Interior, Bureau of Land Macorner points mentioned in of the Michigan Board of established, re-established	chigan PA c rmance with vey instruct anagement c lines 3, 4 au f Land Sur , monument	of 19 n reg tions or by nd 5 veyo ed, r	oro, the culations of the a decrease or by ecovered	corne and Unite e of a vere i y a d, fou	er points rules the ed States Gourt c in confor Decree und as ex	mentione as Departrof Law and mance work of a Cooperate of a Coope	ed in lines 1 required in ment of the d/or that the ith the rules urt of Law; below:		3 4 — 7 5 6 —1 7 8 —1	8	17	- 9	-15	111423	12	
NOTE: Not more than be recorded on this ce		, all	in the s	samo	e town	and ran	ge, may		10 -3	ò	32-	-28	-2 [†]	35-	25	
	1	-4						ration:	134		LL.		<u> </u>			
A. Description of original B1 & B13	l monumer	nt ar	nd acces	ssori	es and/	or subse	quent resto	ration:								
-GLO Resurvey- Set Beech Po Beech 6" N62' Hemlock 16" S -Grand Traverse E.P. Waterman- -DNR Survey-Pla Fd. 4" pipe in roa	ost °E 30 L. :72°W 38 L CoCSR- · Wagon SI :n# R-40-A	 L. 2 kein	-1909			68										
B. Description of corner	evidence f	oun	d and/o	r me	thod ap	plies in r	estoring or	re-esta	ablishin	g corn	er:					
B1 & B13 Standard 1/4 Fd. 4" iron pi to the Towns could be a w	pe with spi	ike i r clo	n centers	r in g L. of	ravel ro E-W gr	d. interse ravel rd.	ction as not is 9' +/- N &	led by CL. o	Ostling f N-S g	ravel re	d. is 4	4' +/-	E. Di	dn't di	g up p	ng's distanc ipe but it
C. Description of monun B1 & B13 - 4" Iron Pipe \$63°E 44.95 N53°E 51.31 \$30°E 123.8 \$82°W 44.30 \$75°E 40' to	w/ spike 5' to set N& ' to set N& 6' to set No 0' to set ½" set Blue C	&T in &T in &T i	n N. side NW sic n W. sic 4" reba onite Pc	e UP le UI le 18 r-Do ost w	o 3" W. Pi wn 0.5' // Loc. T	ne			,	,		of the	TO THE LICENSEI	CR Mc PROF SUF	AIG VEA! VEA! VEA! VEYO NO. 9088	NAL RYON
Signed by: Surveyor's Michigan	License No			3908			Date—	e:	1/22	120	100					
ourveyor a Michigan	CICOTISE INC	٠	_				-									