LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970			
For Corners In: Kalkaska	Located In Corner Co	SU REMON	RVEY & JMENTATION
(County) 1. Public Land Survey	T 27N R 8W A-6	FEB	26 2001
2. Property Controlling in Section	T R S T R		ECTION
Miscellaneous Property in Section	\$T R		amp & File Number
4. Lot No:	Recorded Plat:	A B C D E F G	HIJKLN
requirements of PA 74, Mic and 2 above were in confu- the current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of established, re-established,	field survey on Nov. 1, 1999 do hereby state the chigan PA of 1970, the corner points mentioned it mance with regulations and rules therefore as revey instructions of the United States Department or by a decree of a Court of Law and/or lines 3, 4 and 5 above were in conformance with 1 Land Surveyors or by a Decree of a Court monumented, recovered, found as expressed below 2 corners, all in the same town and range, rtificate.	lines 1 uired in 5 tof the that the re rules of Law; 8 19 20 21	0
A. Description of original monument and accessories and/or subsequent restoration:			
- M. Schaaf – 1930' corner set by mea - MDNR corner recorner recorner recorner in the line with fire line may have been swould fall in Rd. & evidence to contract evidence set 1" 7" R. Pine S64°W	40 L., Aspen 4" S89°W 13 L.; . 18-27- 8 - Survey Bk. 32, P.14 * / Isurement per index ord -K.J. Ostling — 1967 concrete mon. per M. Schaaf —1934. e N,S,E&W et from original evidence although USBT a stp. Have been removed. Unable to find any so accepted this as best available pipe with 4" Alum. cap 40.4", 10" W. Pine N52°E 15.8"	- Consumers Power Company – 1967 P. Found concrete monument LCRC L.3, pg. 614 - Grand Traverse C.F. Roser-1995 - found Conservation 15" Maple N60"W 22.0' 16" W. Pine N50°E 15.6' 8" Maple S60°E 46.4' 9" R. Pine S60°W 40.0' Set cedar post N45"W 16.5'	county record-
B. Description of corner evidence found and/or method applies in restoring or re-establishing corner: A-6. — Standard ¼ corner common to section 13, T27N, R9W & section 18, T27N, R8W — No GLO evidence fd. Set 3 ¼ " 'Grand Traverse Co. Remon.' brass cap on 2 ½ " X 30" galvanized iron pipe by single proportion between A-5 & A-7. Centerline of N-S fire lane is 6.5' West. Centerline of E-W fire line is 24' South. 3 ¼ " brass cap mon. accepted as a careful & faithful reestablishment of the position of the original corner -Reference Pt. —Found DOC (DNR) 4" Alum cap & mon \$22°16"W 25.80" of A-6. This DNR mon. by Ostling is M. Schaaf's position that Schaaf indicates he set by measurement. The M. Schaaf position ½ mile N was rejected as A-5 being \$4*51"W 40.58' of the approved A-5 position. Thus DOC Mon. couldn't be accepted as the proper Single Proportion position for A-6. DNR mon. not utilized as A-6. Removed DNR (DOC) mon. and reset Schaaf 1 ¼ " iron pipe Stub. in conc. tablet in place.			
C. Description of monun	nent for corner and accessories established t	perpetuate locating the position of the co	orner:
Reset 6" cedar po N34"E 17.11 S87"E 36.14 S45"W 62.40 N85"W 22.75 S22"16"W 25.80 Set Blue Carsonit	to set N&T in NW side 9" R. Pine for to set N&T in S side 15" R. Oak scr	bed 'XBT' ibed 'XBT' . scribed '¼ S NBT' bed 'XBT'	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR No. 39088
Signed by:	Wed by the Grand Traverse Cour	Date: //3/2000	POFE SSIONAL SU
Surveyor's Michigan License No.: 39088			
Ratified by Peer P.A. 345 - 1990 Chairman	Kalkaska County	30 Pa 82;	026908 ge: 1 of 1 N. 28, 19; 718/2001 10:28A 39 14, 19; 10N 13An 19;