



8 0 2 5 7 9 7

Tx:4018283

4/1/2013 2:15:00 PM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Kalkaska

(County)

Located In

Corner Code #

| | | | | |
|--------------------------------------|------|-------|------|----|
| 1. Public Land Survey | T | | R | |
| | T | | R | |
| 2. Property Controlling in Section | S 26 | T 28N | R 7W | 1 |
| | S 26 | T 28N | R 7W | 10 |
| 3. Miscellaneous Property in Section | S | T | R | |
| | S | T | R | |

4. Lot No: Recorded Plat:

5. Private Claims:

I, Joshua R. Davidson, in a field survey on September 4, 2012 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1 - W 1/16 corner common to sections 23 & 26

1977 - LCRC, L. 2, P. 76, - C.F. Roser, PS #12028 -
Established 1/16 corner S.P. Corner is 3.5' N of center of E-W gravel road. Drove 1 1/4" X 18" rod.
1) 6" W. Pine N39°E 118.3'
2) 9" Maple S47°E 133.5'
3) 9" Maple S12°E 137.5'
4) Cedar Post w/loc. Tag Due N 33'

10 - S 1/16 corner common to Sections 26 & 27

None

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

1 - W 1/16 corner common to sections 23 & 26

Found 1 1/4" iron bar 5'± North of Centerline East-West gravel road. Found Roser accessories 1, 2, & 3 fitting position.

10 - S 1/16 corner common to sections 26 & 27

Set stamped 2" aluminum cap on 5/8" X 3/4" rebar per BLM standard procedure.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1 - Found 1 1/4" iron bar

N39°E 118.94' to set nail & tag in SW. side 23" W. Pine (#1)
S48°E 134.27' to set N & T in NW. side 6", 13", 13" tri. Maple (#2)
S12°E 137.80' to set nail & tag in W. 15" twin S. Maple (#3)
S12°W 33.65' to set nail & tag in E. side power pole
Set blue carsonite post with location tag 33' North

10 - a stamped 2" Aluminum Cap on 5/8" X 3/4" rebar.

S72°E 94.77' to set nail & tag in S. side tri. 8", 11" twin Cherry
S80°W 15.57' to set nail & tag in S. side 10" R. Pine
S32°W 10.08' to set nail & tag in NW. side 10" R. Pine
N54°W 32.73' to set nail & tag in NE. side 9" R. Pine
Set blue Carsonite post with location tag 1' Southwest

DOCUMENT #

3113015

JOANN DEGRAAF

KALKASKA CTY ROD

KALKASKA, MI

RECORDED ON

04/01/2013 2:57 PM

REC FEE: 14.00

PAGES: 1

BK: 3PG: 354

Register of Deeds Stamp & File Number

| | | | | | | | | | | | | | |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| | A | B | C | D | E | F | G | H | I | J | K | L | M |
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |



Signed by:

Joshua R. Davidson

Date:

4-1-2013

Surveyor's Michigan License No.:

46659