ACITATION INVENTATION

FEB 1 4 1997

_, Recorded Plat

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		KENT COUNTY REMONUMENTATION		(°) + ·····
	Kent (County)	Located in: Caledonia Township	Corner Code #	
1.	Public Land Survey	T R T R T R T R		AM 9: 21
2.	Property Controlling in Section	S <u>9</u> T <u>5N</u> R 10W S T R	West Witness Monument	9500
3.	Miscellaneous Property in Sec.	S T R S T R	883.53' West of G-4	Register of Deeds Stamp & File Number

, in a field survey on Randv Kolehouse June 5 19 96 do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-4A 1831

G.L.O. Notes

Mullett

Corner in "Lake" (River) - Set Temporary Point

1927

Lot No. Private Claims

Notes

Williams & Works

Iron Stake

1992

L.C.R.C. #6567

T. Chettleburgh

Fnd. RR Spike / Set K.C. Monument w/Witness Cap-

11

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by T. Chettleburgh on 5/27/92 and was recorded per L.C.R.C. #6567.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-4A Found a Standard Kent County Monument 2' East of the C/L of Thornapple River Drive, 883.53' West of G-4, T5N, R10W, per L.C.R.C. #6567 as set by T. Chettleburgh in place of a RR spike he found above a 2" iron pipe which checked the 1927 records of Williams & Works.

L.C.R.C. #6567

Remon tag in NW side Power Pole N 68° E 32.55' Remon tag in S side 29" Oak N 90° E 52.77' Remon tag in NE side 19" Oak S 30° E 20.54' Remon tag in SW side 15" Oak S 04° E 36.33' Remon tag in W side 10" Oak S 00° W 46,98'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-4A Standard Kent County Monument

Nail & K.C. remon, tag on NW side Power Pole N 68° E 32,55'

Nail & K.C. remon. tag on S side 29" Oak N 90° E 52.77'

Nail & K.C. remon, tag on NE side 19" Oak S 30° E 20.54'

Nail & K.C. remon. tag on SW side 15" Oak S 04° E 36.33'

Nail & K.C. remon. tag on W side 10" Oak S 00° W 46.98'

Signed by EARTH TECH

Surveyor's Michigan License No.

CHAIRMAN

P.A. 345 1990 KENT COUNTY PEER APPROVE

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1975

OF RANDY 1. KOLEHOUSE LAND SED LAND

REVISED JAN., 1983