

SURVEY & REMONUMENTATION

FEB 14 1997

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 KENT COUNTY REMONUMENTATION

For corners in COMMISSION

Kent (County)	Located in: Caledonia Township	Corner Code #
1. Public Land Survey	T <u>5N</u> R <u>10W</u>	<u>D-10</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	<u>Ref. Monument</u>
	S <u> </u> T <u> </u> R <u> </u>	<u>1341.6' East of D-10</u>
3. Miscellaneous	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

4. Lot No. , Recorded Plat

5. Private Claims

I, Randy Kolehose, in a field survey on October 29 19 96, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

D-10 This corner was not originally set by the G.L.O.

1947	Survey Notes	Williams & Works	3/4" Iron
1973	L.C.R.C. #373	Williams & Works	3/4" Iron

P.A. 345 1990 KENT COUNTY

PEER APPROVED 10/24/96
CHAIRMAN Randy Kolehose

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-10 The 3/4" iron and all witnesses shown in L.C.R.C. #373 have been destroyed. This corner now falls within a building (Lakeview Villa Condominiums). Reestablished 1/4 lines using survey information from Williams & Works (1947). Checks this information $\pm 0.10'$. Computed location for the Center of Section is 3.4' North and 1.5' West of the intersection of 1/4 lines. Set a reference monument 1341.60' East of D-10 using Williams & Works' survey records.

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-10 Set Standard Kent County Reference Monument

SE corner brick pillar at SE porch corner N 47° E 61.92'
Inside corner conc. sidewalk S 41° E 45.30'
NW corner stone fndn. House #131 S 54° W 91.98'
SW corner conc. fndn. House #401 N 46° W 84.05'

Signed by Randy J. Kolehose
EARTH TECH

Date 12/24/96

Surveyor's Michigan License No. 25854

REC. OF DEEDS

9614

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		32		33		34		35		36		
11													
12	31		32		33		34		35		36		
13													

