

JAN 23 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970  
KENT COUNTY REMONUMENTATION

For corners in

Kent (County)	Located in:	Corner Code #
1. Public Land Survey	T <u>5N</u> R <u>12W</u>	<u>B-4</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	<u>Seg #1</u>
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

REG. OF DEEDS

8728

Register of Deeds Stamp & File Number

55 OCT 31 AM 9:00

STATE OF MICHIGAN  
COUNTY OF KENT  
RECEIVED FOR RECORD

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Randy Kolehouse, in a field survey on March 14 19 95, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-4 This corner was not originally set by the G.L.O.

1984 L.C.R.C. #4138

Medema, Van Kooten & Assoc.

Set RR Spike in Root of 24" Maple by  
Int. of 1/4 Lines

P.A. 345 1990 KENT COUNTY

PEER APPROVED 8/24/95

CHAIRMAN Randy Kolehouse

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-4 Found a railroad spike in root of 28" Maple as set by Medema, Van Kooten & Assoc. per L.C.R.C. #4138. Railroad spike is 0.6 North and 0.8 West of intersection of 1/4 lines. Accepted railroad spike as center section.

L.C.R.C. #4138

Sq. spike in E side 24" Maple N 2.45'

Sq. spike in E side 20" Oak S-SE 36.43'

Sq. spike in S side 10" Maple E 6.46'

E & W fence line

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-4 Could not set monument in tree root. Left railroad spike in place.

Sq. spike in E side 24" Maple N 2.45'

Sq. spike in E side 20" Oak S-SE 36.43'

Sq. spike in S side 10" Maple E 6.46'

E & W fence line

Signed by

Randy J. Kolehouse  
EARTH TECH

Date

10/25/95

Surveyor's Michigan License No.

25854

