

Seg 2

\$7.00
\$2.00

JAN 23 1996

COMMISSION LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
KENT COUNTY REMONUMENTATION

For corners in

Kent (County)	Located in:	Corner Code #
1. Public Land Survey	T <u>5N</u> R <u>12W</u>	<u>B-6</u>
	T _____ R _____	
	T _____ R _____	
	T _____ R _____	
2. Property Controlling in Section	S _____ T _____ R _____	<u>Seg 2</u>
	S _____ T _____ R _____	
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	
	S _____ T _____ R _____	

REG. OF DEEDS

Lucy Sand

95 DEC 28 PM 2:18

STATE OF MICHIGAN
COUNTY OF KENT
RECEIVED FOR RECORD

8879

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Randy Kolehouse, in a field survey on March 14 19 95, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-6 This corner was not originally set by the G.L.O.

1898-1966	Wit. Map	K.C. Surveyor	Old Stake
1978	L.C.R.C. #1216	Exxel Engineering	Found 1 1/2 Iron Pipe

P.A. 345 1990 KENT COUNTY

PEER APPROVED 8/24/95

CHAIRMAN *Randy Kolehouse*

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-6 Found a 1 1/2" iron per L.C.R.C. #1216. This iron is 0.4 North and 0.55 East of the intersection of 1/4 lines. Accepted found 1 1/2" iron as Center Section.

L.C.R.C. #1216

Nail in sde 6" W. Cherry NW 13.89'
Nail in sde 14" W. Cherry West 43.61'
Top fence corner post West 13.42'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-6 Replaced the 1 1/2" iron with a standard 4" x 30" Kent County Monument

Nail & K.C. remon. tag in NE side 10" Poplar S 70° E 14.59'
Nail & K.C. remon. tag in SW side 8" Wild Cherry N 40° W 18.17'
Nail & K.C. remon. tag in NW side 20" Maple S 40° W 18.49'
Nail & K.C. remon. tag in N side 18" Wild Cherry S 85° W 43.85'

Signed by *Randy Kolehouse* Date 12/22/95

EARTH TECH

Surveyor's Michigan License No. 25854

