40	SIFFE Filmonum		9 <b>2</b> 83.				र-पार्ट पुरुषा है १५ - १० - १५		
\$2.	Corners market		Filing Require	R RECORDATION C ment of Act 74, Mic JNTY REMONUMEN	h. P.A. 1970	:	ය රෙ /	2	
	Kent (County)		Located in:	Corner Code #		ଅ ମ ଜ	C 8	AESON TOO TAVES	
2. 3.	Public Land Survey Property Controlling in Section Miscellaneous Property in Sec.	s s s	T_5N_ R_12W_ T R T R T R T R T R T R T R	B-13		856		ED FOR RECORD  Number	
4.	Lot No, Recorded Plat								
I,do h menti in the Land 4 and Decre found NOTE	Randy Kolehouse ereby certify that u ioned in lines 1 and 2 current manual of s Management or by a 15 above were in co e of a Court of La I as expressed below  Not more than on this certific  Description of ori  1817 G.L.C 1940 Wit. M 1977 L.C.R 1981 L.C.R 1988 L.C.R	, in a fiender requirement above were in curvey instruction a decree of a Conformance with w; established, and a corners, all cate.  ginal monument of the corners of the curvey of	Id survey onMarc hts of P.A. 74 Michigar conformance with regulat s of the United States D art of Law and/or that the the rules of the Michiga re-established, monum in the same town and ht and accessories and L. Lyon K.C. Surveyor Nederveld & Jonk Nederveld & Jonk Olson, Meyers & I	h 14 10 10 10 10 10 10 10 10 10 10 10 10 10	corner points re as required for, Bureau of ned in lines 3, eyors or by a d, recovered, rded toration: Post ne ns. Power Iron L. C.P. Iron & 2 . Monument	" Iron/Set K.C. Mo	YED 5/2 Yeury pnument	g/g.g Thuper	
	Jonker on 1/19/81	and was record	ved by the Kent Coun led per L.C.R.C. #1562.				d by Nedervo	eld &	
В. В-13	Description of corner evidence found and/or method applied in restoring or reestablishing corner:  Found standard Kent County Monument 2.5' M/L South of the C/L of 108th Street running E-W on line of fences running N-S apparently common with B-1, T4N, R12W, per L.C.R.C.'s #1562 and #4638 as set by Nederveld & Jonker in place of a Consumers Power Company iron over a 2" iron (12" below grade) they found which checked L.C.R.C. #1118.								
	L.C.R.C. #1562			L.C.R.C. #4638					
	Nail & Remon. tag NW cor, hse (brick	on E side P. po ) SE 159.35'	ie S 57.4'	SW cor conc bloc	Nail & Remon tag on E sde P pole S 0 E 57.4' SW cor conc block bldg N 40 E 89.15' NW cor hse (brick) S 50 E 159.35'				
•	The selected locat of the position of the	ion is accepted ne original corne	by me and is generally r.	accepted by professi	ional surveyors	s as the best avai	lable evidenc	e	
C.	Description of monument for corner and accessories established to perpetuate locating the position of the corner:								

B-13 Standard Kent County Monument

Surveyor's Michigan License No. \_\_

Nail & K.C. remon. tag in E side P. pole S 0° E 57.40' NW cor. hse. (brick) S 50° E 159.35' Nail & K.C. remon. tag in E side P. pole N 0° E 47.63' SW cor. conc. block bldg. N 40° E 102.07' C/L 108th Street North 2.5' M/L

\_\_\_\_\_25854

Signed by Ranky & Lole Journe Date 8/21/95

KOLEHOUSE