

STATE OF MICHIGAN
REMONUMENTATION

SEP 13 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
KENT COUNTY REMONUMENTATION

For corners in

Kent (County)	Located in:	Corner Code #
1. Public Land Survey	T <u>5N</u> R <u>12W</u>	<u>C-9</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

REC. OFFICERS

8572

STATE OF MICHIGAN
COUNTY OF KENT
RECEIVED FOR RECORD
95 AUG 28 AM 10:48

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Randy Kolehouse, in a field survey on March 14 19 95,
do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required
in the current manual of survey instructions of the United States Department of the interior, Bureau of
Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3,
4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered,
found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-9	1831	G.L.O. Notes	Mullett	Set Post
	1949	Wit. Map	K.C. Surveyor	Stone & 3" Iron
	1963	Wit. Map	K.C. Surveyor	Iron in Monument Box
	1973	L.C.R.C. #638	Exxel Engineering	2" Iron in Monument Box
	1981	L.C.R.C. #1571	Nederveld & Jonker	Fnd. 2" Iron in M.B./Set K.C. Monument
	1988	L.C.R.C. #4622	Olson, Meyers & May	K.C. Monument

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Nederveld & Jonker on 1/12/81 and was recorded per L.C.R.C. #1571.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-9 Found standard Kent County Monument in a monument box per L.C.R.C.'s #1571 and #4622 2.5' M/L West of the C/L of Wilson Avenue running N-S and 2' M/L North of the C/L of 92nd Street running E-W as set by Nederveld & Jonker in place of a 2" iron in the monument box they found which checked L.C.R.C. #638.

L.C.R.C. #1571

Nail & K.C. Remon. tag on NE side T. pole SE 58.5'
Nail & K.C. Remon. tag on S side fence post NE 59.78'
Nail & K.C. Remon. tag on E side P. pole SSW 141.9'
Nail & K.C. Remon. tag on NW side P. pole NW 50.59'

L.C.R.C. #4622

Nail & K.C. Remon. tag on NE sde T pole S 65 E 58.5'
Nail & K.C. Remon. tag on S sde fence pole N 40 E 59.78'
Nail & K.C. Remon. tag on E sde P pole S 15 W 141.9'
Nail & K.C. Remon. tag on SW sde P pole N 50 W 50.59'
Face of conc R.O.W. marker S 10 E 102.76'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-9 Standard Kent County Monument in a Monument Box

Nail & K.C. remon. tag on NE side T. pole S 65° E 58.50'
Nail & K.C. remon. tag on SW side P. pole N 50° W 50.59'
Nail & K.C. remon. tag on S side fence post N 40° E 59.52'
Nail & K.C. remon. tag on E side P. pole S 15° W 142.02'
Face conc. R.O.W. marker S 10° E 102.00'

Signed by Randy J. Kolehouse
EARTH TECH

Date 8/21/95

Surveyor's Michigan License No. 25854

