

\$7.00  
\$2.00

SURVEY &  
MONUMENTATION

JAN 23 1996

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

COMMISSION

KENT COUNTY REMONUMENTATION

Kent  
(County)

Located in:

Corner Code #

1. Public Land Survey T 5N R 12W D-4  
T R  
T R  
T R  
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R

4. Lot No. , Recorded Plat  
5. Private Claims

REG. OF DEEDS

8884

95 DEC 28 PM 2:18

STATE OF MICHIGAN  
COUNTY OF KENT  
RECEIVED FOR RECORD

Register of Deeds Stamp & File Number

I, Randy Kolehhouse, in a field survey on March 15 19 95, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- D-4 1912 Survey Notes Williams & Works Found & Accepted Leaded Stone  
1957-1959 Survey Notes Williams & Works Set RR Spike at Int. of 1/4 Lines  
1961-1965 Survey Notes Williams & Works Set "T" Iron per Wit. for RR Spike Above  
1972 L.C.R.C. #51 Medema, Van Kooten & Assoc. Found "T" Iron within 1" of True Int. of 1/4 Lines - Accepted

P.A. 345 1990 KENT COUNTY

PEER APPROVED 8/24/95

CHAIRMAN Randy Kolehhouse

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- D-4 Found "T" iron 5.0' East of C/L of Homerich Avenue per L.C.R.C. #151 as accepted by MVK which they found to be within 1' of true 1/4 line intersection. "T" iron is 1.1' South and 0.10' East of the intersection of 1/4 lines. Measurements E-W & N check record measurements from Williams & Works & Jonker Land Surveys.

L.C.R.C. #151

SE cor. hse. W-SW 108.25'  
NE cor. garage NW 147.03'  
SW cor. garage NE 94.08'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- D-4 Replaced "T" iron with a standard 4" x 30" Kent County Monument

Nail & K.C. remon. tag in W side 12" Ash S 12° E 81.44'  
Nail & K.C. remon. tag in S side P. pole N 60° W 38.40'  
SE corner hse. fndn. N 70° W 108.25'  
NE corner garage fndn. N 42° W 147.15'  
SW corner garage fndn. N 63° E 93.87'

Signed by Randy J. Kolehhouse Date 12/22/95

EARTH TECH

Surveyor's Michigan License No. 25854

