

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
KENT COUNTY REMONUMENTATION

For corners in

Kent
(County)

Located in:

Corner Code #

1. Public Land Survey

T 5N R 12W G-1

2. Property Controlling
In Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

REG. OF DEEDS

8604

95 AUG 28 AM 10:51

STATE OF MICHIGAN
COUNTY OF KENT
RECEIVED FOR RECORD

Register of Deeds Stamp & File Number

I, Randy Kolehose, in a field survey on March 24 19 94,
do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required
in the current manual of survey instructions of the United States Department of the interior, Bureau of
Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3,
4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered,
found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-1	1831	G.L.O. Notes	L. Lyon	Set Post	P.A. 345 1990 KENT COUNTY
	1933	Wit. Map	K.C. Surveyor	"+" in Pavement	PEER APPROVED 8/24/95
	1957	Wit. Map	K.C. Surveyor	Iron in M.B.	CHAIRMAN <u>Harry Kule</u>
	1975	L.C.R.C. #894	Exxel Eng.	Iron in M.B.	
	1981	L.C.R.C. #1685	Williams & Works	End Iron in M.B./Set KC Mon.	

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Williams & Works,
Inc., on 5/1/81 and was recorded per L.C.R.C. #1685

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-1 Found KC Monument in centerline of Byron Center Ave. running N-S per L.C.R.C. #1685 as set by Williams & Works in place
of a 3/4" iron in M.B. which they found and checked with 1933 and 1957 Wit Map and L.C.R.C. #894.

L.C.R.C. #1685

Nail & K.C. remon. tag E side 38" Sycamore N 30° E 59.09'
Nail & K.C. remon. tag S side 8" Elm S 50° E 44.46'
Nail & K.C. remon. tag S side 4" Elm N 70° E 43.23'
Top C/L con. ROW mon. East 18.77'
SE leg of C.P. tower (at ground) S 25° W 131.08'
NW leg of C.P. tower (at ground) S 55° W 128.28'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence
of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-1 Standard Kent County Monument

Nail & K.C. remon. tag E side 38" Sycamore N 30° E 59.09'
Nail & K.C. remon. tag S side 8" Elm S 50° E 44.27'
Nail & K.C. remon. tag S side 4" Elm N 70° E 46.94'
SE leg of C.P. tower (at ground) S 25° W 131.08'
NW leg of C.P. tower (at ground) S 55° W 128.28'

Signed by

Randy J. Kolehose
EARTH TECH

Date

8/21/95

Surveyor's Michigan License No.

25854