\$77	
\$2.	,

SEP 1 3 1995

	LAND CORNER RECORDATION CERTIFICATE
Commession	Filing Requirement of Act 74, Mich. P.A. 1970

Eor	corners in	COMMISSION		rement of Act 74, Mich. I		-c1	1 25	限の当	
1 01			: i	•	1		\ E	밀얼작	
	Kent (Co	unty)	Located in:	Corner Code #		- 6	28		
1.	Public Lan	d Survey	T <u>5N</u> R <u>12W</u> T R R	G-3		F DEEDS	7 7 7 7 7 7 7 7 7 7 7	TOP MENT	-
	Property C in Section	s	TR			\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		©	
3.	Miscellane Property in		TR TR		Regia	ster of Deeds Sta	amp & File	Number	
4. 5.	Lot No Private Cla	, Records	ed Plat			A B C D E	F G H	ı J K	
			•			2 5	-43-		-
men in th Land 4 an Decr	nereby certifitioned in line e current mad Manageme ad 5 above v ree of a Co d as express E: Not m on thi	y that under required is 1 and 2 above were anual of survey instruction to roy a decree of a vere in conformance where the conformance con	ments of P.A. 74 Michic in conformance with regulations of the United States Court of Law and/or that with the rules of the Michined, re-established, montal all in the same town as	pan P.A. of 1970, the correlations and rules therefore as Department of the interior, the corner points mentioned gan Board of Land Surveyor mented, re-monumented, rend range, may be recorded	ner points s required Bureau of in lines 3, rs or by a ecovered,	3 4 7 8 5 5 6 18 17 7 7 7 8 8 19 20 9 9 10 30 29 11 12 31 32		23	13
Α.	Descripti	on of original monu	ment and accessories	and/or subsequent restora		12.1.3.5	-! 	CHTY	
G-3	1831	G.L.O. Notes	Mullett	Set Pos	st	PEER APPRO	VED 2/	<u> </u>	/
	1959	Wit. Map	K.C. Surveyor	Monum	nent Box	CHAIRMAN /	fare	47/	uhi
	1971	L.C.R.C. #39	Williams & Wo	ks Fnd 3/	4" Iron in Mon	ı. Box		•	
	1981	L.C.R.C. #1524	Exxel Engineer	ing Fnd. 3/	4" Iron in Mon	n. Box/Set K.C. M	onument		
	1988	L.C.R.C. #4606	Olson, Meyers	& May K.C. Me	onument				

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Exxel Engineering on 12/4/80 and was recorded per L.C.R.C. #1524.

- В. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- G-3Found standard Kent County Monument on C/L of Byron Center Avenue per L.C.R.C.'s #1524 and #4006 as set by Exxel Engineering in place of a 3/4" iron in monument box they found which checked L.C.R.C. #39 and K.C. Surveyor's Wit. Map (1959).

L.C.R.C. #1524

L.C.R.C. #4606

PK nail on top conc. headwall S89°E 30.80' PK nail on top conc. headwall N59°W 35.71' Nail & tag in N sde 10" Maple S53°W 74.03'

PK nail on top conc hdwl S 89 E 30.80' PK nail on top conc hdwl N 59 W 35.71' Nail & Remon tag in N sde 12" Maple S 53 W 74.03'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the

G-3 Standard Kent County Monument

> Nail & K.C. remon. tag on N side P. pole S 85° W 43.38' Nail & K.C. remon. tag on N side 12" Maple S 53° W 74.15' P.K. nail on top conc. headwall N 59° W 35.71

P.K. nail on top conc. headwall S 89° E 30.80'

KOLEHOUSE

Surveyor's Michigan License No. 25854