	f francis or					
37	į.	EP 1 8 1995				
\$2. _	****		LAND CORNER RECORD Filing Requirement of Ad KENT COUNTY REM	et 74, Mich. P.A. 1970	The same of the sa	(/)
For c	orners in			1		
	Kent (Cou	nty)	Located in: Corner C	Jode #	REG. OF	(1) Ta
	,			Ì	S(2/2 ≥ 229)	
 Public Land Survey 		Survey	T 5N R 12W G-	4	ANIO: RESE	
		•	TR		5 5 5 B	ir.
	-		T R		/ 2 5	
2. I	Property Co	ntrolling S	_ T R		OCOM	
	n Section	S	_TR	•	8607	,·*
	Miscellaneo		_ T R _ T R	. Re	gister of Deeds Stamp & File Numb	er
ì	Property in \$	sec. s	- '			-
4 I	ot No	Recorded	Plat	•		
		ms			ABCDEFGHIJ	K L
					2 6 5 4 3 - 2	
					3	
t.	Randy Kole	ehouse , in a fi	eld survey onApril 12	19 95,	4	12
do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points						
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of						
Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3,						
4 and	15 above w	ere in conformance with	n the rules of the Michigan Board of d, re-established, monumented, re-n	Land Surveyors or by a	8 19 20 21 22 23	24-
	as expresse		, 16-established, Illohumented, 16-n	ionamentod, resovered,	9	
NOTE	E: Not me	ore than 4 corners, a	I in the same town and range, ma	y be recorded	10 30 29 28 27 26	25
	on this	s certificate.			12 31 32 33 34 35	36
А.	Description	on of original monum	ent and accessories and/or subse	equent restoration:	13	
Λ.	Description	on or original monant	:	,	P.A. 345 1990 KENT COUI	VTY
G-4	1831	G.L.O. Notes	Mullett	Set Post	PEER APPROVED 5/25	199
	N/A	Wit. Map	K.C. Surveyor	Monument Box	BCHAIRMAN Faur	bul
	1971 1972	L.C.R.C. #38 L.C.R.C. #199	Williams & Works Williams & Works	Fnd : from in Mon	on, Box	
	1974	L.C.R.C. #771	Nederveld	Fnd, 3/4" Iron in M		
	1980	L.C.R.C. #1531	Exxel Engineering		n. Box/Set K.C. Monument	
	1988	L.C.R.C. #4607	Olson, Meyers & May	K.C. Monument		
		er was originally appro 0 and was recorded pe		entation Peer Group and	monumented by Exxel Engineering	İ
В.	Description	on of comer evidence	found and/or method applied in	restoring or reestablishin	ng corner:	
G-4	W per L.0	C.R.C.'s #1531 and #4	onument on C/L intersection of Byrd 607 as set by Exxel Engineering i and #771 and K.C. Surveyor's Wit. I	n place of a 3/4" iron in a	N-S and 72nd Street running E- monument box they found which	
	1	C.R.C. #1531	L.	C.R.C. #4607		
				op curb N 49 W 38.31'		
	PK nail in top curb N49°W 38.31' NW cor hse fndn S45°E 109.01'		NW cor hs	e fndn S 45 E 109.01' Remon tag in NW sde T	pole N 55 E 58.94'	
		eted location is accepte sition of the original cor	ed by me and is generally accepted mer.	by professional surveyors	s as the best available evidence	
C.	Descripti	on of monument for c	orner and accessories establishe	d to perpetuate locating	the position of the corner:	
C 4	Chandral	Vant Caumba Manus		•	STATE MICHAEL	4 0.
G-4	Glandard	Kent County Monume			HALL	P. S.
		. nail top curb N 49° W		·	RANDY J.	
			SE side P. pole S 60° W 42.65'		KOLEHOUSE	*
		& K.C. remon. tag on cor. hse, fndn. S 50° E	NW side T. pole N 55° E 58.85′		SURVEYOR No.	3
			NE side T. pole S 33° E 63.88'		25854	10

25854

Signed by

Surveyor's Michigan License No.