

200 2003

CONCLUSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
KENT COUNTY REMONUMENTATION

For corners in

Kent
(County)

Located in:

Corner Code #

1. Public Land Survey

T 5N R 12W

H-5

2. Property Controlling in Section

S _____ T _____ R _____

3. Miscellaneous Property in Sec

S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____

5. Private Claims

I, Randy Kolehous, in a field survey on April 7 19 95, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H-5	1831	G.L.O. Notes	Mullett	Set Post
	1963	Wit. Map	K.C. Surveyor	Monument E
	1972	L.C.R.C. #150	Medema, Van Kooten & Assoc.	Found Iron i
	1980	L.C.R.C. #1526	Exxel Engineering	Found Iron i
	1991	L.C.R.C. #6321	Chris Marschall	K.C. Monum

P.A. 345 1930 KENT COUNTY

PEER APPROVED 5/29/98

CHAIRMAN Harold P. ...

Box

Box/Set K.C. Monument

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Exxel Engineering on 12/1/80 and was recorded per L.C.R.C. #1526.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-5 Found standard Kent County Monument in monument box 0.8' North of C/L of 16th Street running E-W per L.C.R.C.'s #1526 and #6321 as set by Exxel Engineering in place of an iron in monument box they found which checks L.C.R.C. #150 and K.C. Surveyor's Wit. Map.

L.C.R.C. #1526

L.C.R.C. #6321

Nail & tag in SW Sde 30" Maple (2' above ground)
N50°W 124.55'

Nail & Tag NE sd. U.P. N 61 W 71.71'

Nail & Tag W sd. U.P. S 00 W 34.41'

Nail & Tag SW sd. 34" Maple N 50 W 124.53'

Nail & Tag NE sd. 30" Maple S 35 E 129.85'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-5 Standard Kent County Monument

Nail & K.C. remon. tag on NE side Utl. pole N 61° W 71.71'
Nail & K.C. remon. tag on W side Utl. pole S 00° W 34.41'
Nail & K.C. remon. tag on SW side 34" Maple N 50 W 124.53'
Nail & K.C. remon. tag on NE side 30' Maple S 35° E 129.85'
Nail & K.C. remon. tag on SE side 6" Maple N 62° E 90.87'

Signed by Nancy J. Kalkbrenner

Date _____

8/21/95

Surveyor's Michigan License No. 25854