

1/2
JAN 29 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
KENT COUNTY REMONUMENTATION

For corners in

Kent
(County)

Located in:

Corner Code #

1. Public Land Survey T 5N R 12W H-8
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____
4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

STATE OF MICHIGAN
COUNTY OF KENT
RECEIVED FOR RECORD
95 OCT 31 AM 9:02
REG. OF DEEDS
8737

Register of Deeds Stamp & File Number

I, Randy Kolehouse, in a field survey on April 20 19 95, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H-8 This corner was not originally set by the G.L.O.

1904	Survey Notes	Williams & Works	Found and Accepted Post
1926	Survey Notes	Williams & Works	Found and Accepted Pile of Stones
1946-1957	Survey Notes	Williams & Works	Found and Accepted Intersection of Fences
1980	L.C.R.C. #1390	Exxel Engineering	Set Capped Iron at Int. of the 1/4 Lines

P.A. 345 1990 KENT COUNTY

PEER APPROVED 8/24/95

CHAIRMAN Harry Hubers

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-8 Found capped iron 4-5' West of fence corner running N-S, E & W per L.C.R.C. #1390 as set by Exxel Engineering at the intersection of 1/4 line. This point could be 4.5' M/L West of the Center Section as shown in 1904 Williams & Works notes and Williams & Works surveys 1904-1957 which noted the fence corner. Capped iron is 0.2' North and 0.1' East of the intersection of 1/4 lines. Accepted iron as the Center Section.

L.C.R.C. #1390

Nail in E side 10" Ash North 21.25'
Nail in N side 24" Ash N 85° E 15.89'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-8 Replaced the Capped Iron with a Standard 4" x 30" Kent County Monument

Nail & K.C. remon. tag in W side 12" Ash South 31.98'
Nail & K.C. remon. tag in W side 8" Elm North 4.79'
Nail & K.C. remon. tag in E side 10" Ash N 21.25'
Nail & K.C. remon. tag in N side 24" Ash N 85° E 15.98'
Fence corner East 4.5'

Signed by Randy J. Kolehouse
EARTH TECH

Date 10/25/95

Surveyor's Michigan License No. 25854

