

COMMISSION

Ear	corners in			Filing Requ		74, Mich. P.A. 1 NUMENTATION	970		١	95	A .	(25	
LOI								:37 111	استر		83	;! }`>-	
******	Kent (Co	ounty)	Locate	a in:	Corner C	ode#		ඩ ආ භ	25	6 28	NEW YORK	터 유	
1.	Public Lan	d Survey	Т Т	R 12W R	1-1			PEEDS!		Ö Z			
2.	Property C	Controlling	ST ST	R				\ 8(324	<u>5</u> 7	5 -	, i	
3.	Miscellane	ous	s T		Pogleter of Door					ds Stamp & File Number			
	Property in	Sec.	s T	R			negist	let of Dee		O T HO	Hamb		
4, 5.	Lot No	, Re	corded Plat	: []				A B C	D E F	G H	į J	KLI	
٥.	i iivato oto												
						3	2		-54-	Ti-			
				· -			3						
! <u> </u>	Randy Ko	lehouse,	in a field surv	ey onN	March 2	19 95	_ ' 4	7-1-	9-	10-	 "	12-	
do f	nereby certi	fy that under re	quirements of	P.A. 74 Mich	igan P.A. of 19	370, the comer posts therefore as requ	ints 5			-			
						is the interior, Burea		B	-1716-	15-			
						ts mentioned in line					++		
4 an	d 5 above v	were in conforma	nce with the rul	es of the Mich	nigan Board of L	and Surveyors or b	ya 🛚 🕫	19-	-20			24	
			ablished, re-est	ablished, mor	numented, re-mo	onumented, recove	red, 9						
	d as expres	•		· .			10	30	-29		26-	25	
NOT		nore than 4 cor	ners, all in the	same town	and range, may	be recorded	- 11			\bot			
	on th	is certificate.		j. II.			12				.	78	
Α.	Descript	ion of original n	nonument and	accessories	and/or subseq	uent restoration:		345 195	T T				
•	•			-:			. DEEL	R APPR	aven 4	1/25	105	ı	
I-1	1817	G.L.O. Notes	s i	Lyons		Set Post			0 / D 2	1011	ht		
	1965	Wit, Map	ı	C.C. Surveyor	•	3/4" Iron	CHA	IRMAN,	7 ten	y	pu	Siev	
	1974	L.C.R.C. #67		Exxel Engine		Found 3/4" li							
	1981	L.C.R.C. #18		Exxel Engine		Found 3/4" la		C. Monur	nent				
	1988	L.C.R.C. #47	737 (Olson, Meyers	s & May	K.C. Monum	ent						
		ner was originally I and was record			nty Remonume	ntation Peer Group	and mor	numented	by Exxe	Engin	eering		
B.	Descript	ion of corner ev	ridence found	and/or metho	d applied in re	storing or reestab	olishing c	orner:					
1-1	per L.C.	R.C.'s #1822 ar	nd #4737 as se	t by Exxel E	ngineering in pl	me Avenue runnir ace of a 3/4" iron of the SE cor., Se	they foun	d which	checks L.		-		
		L.C.R.C.	#1822	# ## ## ## ## ## ## ## ## ## ## ## ## #	•	L.C.R.C. #47	37						
	Nail & KC tag in SE sde 14" Maple S61°W 41.37' SE corner house fndn at ground N16°W 193.35' Nail & KC tag in W sde 7" Apple N58°E 87.42'				Nail & Remon tag in SE sde 16" Maple S 61 W 41.37' Nail & K.C. Remon tag in W sde 9" Apple N 58 E 87.42' Nail & Remon tag in SW sde P pole N 40 W 77.06' SE cor hse #5971 fndn at ground N 16 W 193.35' K.C. Mon (SE 34 T6N, R112W) East 11.0'								
		cted location is a sition of the origi		and is gener	rally accepted b	y professional sur	veyors as	the best	available	eviden	ice		
C.	Descript	ion of monumer	nt for corner ar	nd accessorie	es established	to perpetuate loc	ating the	position (of the co	ner:	1 K F# # # 2 pr.		
l-1	Standard Kent County Monument								ر در	E OF	MIC	I Care	
	Nai	il & K.C. remon.	tag on SF side	16" Manle S	61° W 41.37'				3 65		VDY J.	. 7	
		il & K.C. remon.							•		EHOUS E		
		il & K.C. remon.									.AND IVEYO <mark>R</mark>	ž ★	
		cor. hse. #5971	-						و الما الما الما الما الما الما الما الم		No.		
		. top hyd. S 55° l		1					Co	~ Z5	854	· COL	
	K.C	C. Mon. (SE 34 T	6N R12W) E 1	1.0'					***	Sto .	AND SY	Rycies	
		D- 1	20 W	11			0/-	./	<u> </u>	*******	111111111	1432	
Sign	ed by	years	EARTH TECH	wear		Date	8/2/	195					
		•	V	, t _i									

25854

Surveyor's Michigan License No. ___