

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 KENT COUNTY REMONUMENTATION For corners in Located in: Corner Code # Kent (County) **Public Land Survey** T<u>5N</u> R R **Property Controlling** R in Section Miscellaneous Register of Deeds Stamp & File Number Property in Sec. , Recorded Plat Private Claims , in a field survey on Randy Kolehouse April 6 19 do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 12 Description of original monument and accessories and/or subsequent restoration: P.A. 345 1990 KENT ÇOUNT 1-3 1831 G.L.O. Notes Mullett Set Post PEER APPROVED 5/25 1949 Wit. Map K.C. Surveyor Leaded Stone CHAIRMAN Wit. Map K.C. Surveyor 3/4" Iron 1962 1972 L.C.R.C. #421 Medema, Van Kooten & Assoc. Found 1/2" Iron 1980 L.C.R.C. #1541 Exxel Engineering Found 1" Iron and Stone in Mon. Box/Set K.C. Monument 1992 L.C.R.C. #6327 Chris Marschall K.C. Monument This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Exxel Engineering on 12/19/80 and was recorded per L.C.R.C. #1541. 8. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1-3 Found standard Kent County Monument on C/L of 68th Street running E-W and 2.0' West of C/L of Burlingame Avenue running N-S per L.C.R.C.'s #1541 and #6327 as set by Exxel Engineering in place of a 1" iron and stone they found which checks L.C.R.C. #421 and K.C. Surveyor's Wit. Map. L.C.R.C. #1541 L.C.R.C. #6327 Nail & tag in NW sde 12" Oak (2.5' above ground) Nail & Tag N sd. 32" Oak S 87 E N46°E 34.21' Nail & Tag NW sd. 20" Oak N 46 E 34,42" Nail & tag in N sde 30" Maple (2.5' above ground) Nail & Tag N sd. 34" Maple S 87 W 78.15' S87°W 78.37' Nail & Tag NE sd. Twin 12" - 4" Maple (2' above grd.) N 37 W 27.55' Nail & Tag E sd. 16" Maple S 22 W 64.31' Nail & Tag W sd. 12" Maple S 09 E 142.70' The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. Description of monument for corner and accessories established to perpetuate locating the position of the corner: nF Standard Kent County Monument Nail & K.C. remon. tag on N side 32" Oak S 87 E RANDY J.

of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1-3 Standard Kent County Monument

Nail & K.C. remon. tag on N side 32" Oak S 87° E

Nail & K.C. remon. tag on NW side 20" Oak N 46° E 34.42'

Nail & K.C. remon. tag on N side 34" Maple S 87° W 78.15'

Nail & K.C. remon. tag on NE side 16" Maple S 22° W 64.31'

Nail & K.C. remon. tag on E side 16" Maple S 22° W 64.31'

Nail & K.C. remon. tag on W side 12" Maple S 00° E 142.70'

Signed by

APPLITECH

Surveyor's Michigan License No.

25854

FORM APPROVED BY MICHGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1071

REVISED JAN. 1893