

SEP 13 1995

\$7.00
\$2.00

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
KENT COUNTY REMONUMENTATION

For corners in

Kent
(County)

Located in:

Corner Code #

1. Public Land Survey

T 5N R 12W

I-5

2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous
Property in Sec.

S T R
S T R

4. Lot No. , Recorded Plat

5. Private Claims

STATE OF MICHIGAN
COUNTY OF KENT
RECEIVED FOR RECORD
95 AUG 28 AM 10:52
REG. OFFICERS
Lucy Bond
8628
Register of Deeds Stamp & File Number

I, Randy Kolehouse, in a field survey on April 6 19 95,
do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required
in the current manual of survey instructions of the United States Department of the Interior, Bureau of
Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3,
4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered,
found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-5	1831	G.L.O. Notes	Mullett	Set Post
	1963	Wit. Map	K.C. Surveyor	"X" in Pavement
	1971	L.C.R.C. #40	Williams & Works	Found 1/2" Iron in Mon. Box
	1980	L.C.R.C. #1543	Exxel Engineering	Found 1" Iron in Mon. Box/Set K.C. Monument
	1992	L.C.R.C. #6329	Chris Marshall	K.C. Monument

P.A. 345 1990 KENT COUNTY

PEER APPROVED 5/29/95
CHAIRMAN *Harry Shubert*

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Exxel Engineering
on 12/23/80 and was recorded per L.C.R.C. #1543.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-5 Found standard Kent County Monument at C/L intersection of 76th Street running E-W and Burlingame running N-S per
L.C.R.C.'s #1543 and #6329 as set by Exxel Engineering in place of a 1" iron in monument box they found which checked
L.C.R.C. #40 and K.C. Surveyor's Wit. Map.

L.C.R.C. #1543

L.C.R.C. #6329

NE'y cor brick house (2' above ground) S30°W 153.82'	Nail & Tag NE sd. 14" Pine N 36° E 69.98'
	NE'y corner brick hse (2' above grd) S 30° W 153.81'
	Nail & Tag NW sd. U.P. S 46° W 48.67'
	Nail & Tag NE sd. Guy Pole N 45° E 46.58'
	Centerline Top Nut Hydrant N 73° E 65.67'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence
of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-5 Standard Kent County Monument

Nail & K.C. remon. tag on NE side 14" Pine N 36° E 69.98'
NE'y corner brick house (2' above ground) S 30° W 153.81'
Nail & K.C. remon. tag on NW side Util. pole S 46° W 48.67'
Nail & K.C. remon. tag on NE side Guy pole N 45° E 46.58'
C/L top nut hydrant N 73° E 65.67'

Signed by *Randy J. Kolehouse*
EARTH TECH

Date 8/21/95

Surveyor's Michigan License No. 25854

