

SEP 13 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
KENT COUNTY REMONUMENTATION

For corners in

Kent
(County)

Located in:

Corner Code #

- | | | | |
|------------------------------------|------|-------|-----|
| 1. Public Land Survey | T 5N | R 12W | M-2 |
| | T | R | |
| | T | R | |
| | T | R | |
| 2. Property Controlling in Section | S | T | R |
| | S | T | R |
| 3. Miscellaneous | S | T | R |
| Property in Sec. | S | T | R |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

REC. OF DEEDS

8665

Register of Deeds Stamp & File Number

I, Randy Kolehuse, in a field survey on March 15 19 95, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-2	1831	G.L.O. Notes	Mullett	Set Post
	N/A	Wit. Map	K.C. Surveyor	Stake C/L Pavement
	1972	L.C.R.C. #210	Exxel Engineering	Found 1" Iron in Mon. Box
	1973	L.C.R.C. #645	Medema, Van Kooten & Assoc.	Found 1" Iron in Mon. Box
	1981	L.C.R.C. #1612	Exxel Engineering	Found 1" Iron in Mon. Box/Set K.C. Monument
	1991	L.C.R.C. #6362	Chris Marschall	K.C. Monument

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Exxel Engineering on 1/30/81 and was recorded per L.C.R.C. #1612.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-2 Found standard Kent County Monument in the C/L of Division Avenue running N-S and 150' M/L North of Carriage Lane running West per L.C.R.C. #210 and #6362 as set by Exxel Engineering in place of a 1" iron in monument box they found which checked L.C.R.C.'s #210 and #645.

L.C.R.C. #210

Nail in N side P. Pole W 26.89'
Nail in S side T. Pole ESE 49.51'

L.C.R.C. #6362

Nail & Tag S. sd U.P. N 85 W 26.70'
SE corner Bldg. #6375 on brick S 70 W 113.45'
Nail & Tag N. sd U.P. N 90 E 42.89'
Centerline top nut hydrant S 45 W 96.76'
SW corner Bldg. #6364 brick N 60 E 124.46'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-2 Standard Kent County Monument

Nail & K.C. remon. tag on S side Utl. pole N 80° W 26.70'
Nail & K.C. remon. tag on N side Utl. pole N 83° E 42.92'
SE cor. bldg. #6375 on brick S 80° W 113.40'
SW cor. bldg. #6364 on brick N 73° E 124.46'
C/L top nut on hydrant S 42° W 96.74'

Signed by

Randy J. Kolehuse
EARTH TECH

Date

8/21/95

Surveyor's Michigan License No.

25854