

SEP 19 1995

COMMISSIONER

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
KENT COUNTY REMONUMENTATION

For corners in

Kent
 (County)

Located in:

Corner Code #

1. Public Land Survey

T 5N R 12WM-12

T _____ R _____

T _____ R _____

T _____ R _____

2. Property Controlling
in Section

S _____ T _____ R _____

S _____ T _____ R _____

3. Miscellaneous
Property in Sec.

S _____ T _____ R _____

S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

REG. OF DEEDS

Lucy Land

95 AUG 28 AM 10:55

STATE OF MICHIGAN
COUNTY OF KENT
RECEIVED FOR RECORD

8675

Register of Deeds Stamp & File Number

I, Randy Kolehhouse, in a field survey on March 17 19 95,
 do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points
 mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required
 in the current manual of survey instructions of the United States Department of the Interior, Bureau of
 Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3,
 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a
 Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered,
 found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
 on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

M-12	1831	G.L.O. Notes	Mullett	Set Post
	N/A	Wit. Map	K.C. Surveyor	Iron Pipe
	1981	L.C.R.C. #1817	Exxel Engineering	Found 1" Steel Bolt on C/L Pavement/Set K.C. Monument
	1992	L.C.R.C. #6372	Chris Marschall	K.C. Monument

P.A. 345 1990 KENT COUNTY

PEER APPROVED 6/27/95CHAIRMAN Harry Huber

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Exxel Engineering
 on 5/4/81 and was recorded per L.C.R.C. #1817.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-12 Found standard Kent County Monument on C/L of Division Avenue running N-S per L.C.R.C.'s #1817 and #6372 as set by
 Exxel Engineering in place of a 1" steel bolt they found which checked K.C.R.C. Wit. Map. This point is 15.24' South of the A-
 12, T5N R11W.

L.C.R.C. #1817

L.C.R.C. #6372

Nail & KC tag in N sde P. Pole S85°W 86.32'

Nail & KC tag in NE sde fence post N33°W 61.43'

1" iron at W 1/4 corner, Section 31 North 15.24'

Nail & Tag in N sd P.P. S 85 W 86.31'

Nail & Tag in NE sd Fence post N 33 W 61.27'

Nail & Tag in E sd 4" Elm clump S 53 W 32.86'

Nail & Tag in SE sd fence post S 89 W 34.42'

C/L of 3" Oak N 42 W 47.17'

A-12 T5N R11W N 0 E 15.22'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence
 of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-12 Standard Kent County Monument

Nail & K.C. remon. tag on N side P. pole S 85° W 86.31'

Nail & K.C. remon. tag on NE side fence post N 33° W 61.27'

Nail & K.C. remon. tag on E side 4" Elm clump S 53° W 32.86'

Nail & K.C. remon. tag on SE side fence post S 89° W 34.42'

C/L of 3" Oak N 42° W 47.17'

A-12 T5N R11W N 0° E 15.22'

Signed by Randy J. Kolehhouse Date 8/21/95

EARTH TECH

Surveyor's Michigan License No. 25854