

JAN 2 3 1996

LAND CORNER RECORDATION CERTIFICATE

	•	MOISSININO:		it <mark>of Act 74, Mich. P.A. 19</mark> Y REMONUMENTATION	
FOR	corners in			1	DEC 28
	Kent (County)	l_oca	ted in: C	orner Code #	
1.	Public Land Surve	T T	5N R_12W R R R R	H-8	FOR RECORD 8 PM 2: 18 OF DEEDS
	Property Controllii	ng ST_	R R	20.2	8890
	Miscellaneous		R	7	,
	Property in Sec.		R		Register of Deeds Stamp & File Number
I, do h ment in the Land 4 and Decre found	Randy Kolehouse ereby certify that ioned in lines 1 and courrent manual of Management or by 5 above were in see of a Court of that as expressed belowere the court of the cour	, in a field su under requirements of 2 above were in confor survey instructions of a decree of a Court of conformance with the reaw; established, reserver.	rvey on <u>April 20</u> f P.A. 74 Michigan P., rmance with regulations the United States Depar Law and/or that the conules of the Michigan Bostablished, monumente	19 95 A. of 1970, the corner point and rules therefore as require transport of the interior, Bureau ner points mentioned in lines ard of Land Surveyors or by d, re-monumented, recovere	nts
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.					11
A.	Description of c	priginal monument an	d accessories and/or	subsequent restoration:	12 31 32 33 34 35 36
H-8	This corner was	not originally set by th	e G.L.O.		
	1904	Survey Notes	Williams & Work	s Found and Ac	cepted Post
	1926	Survey Notes	Williams & Worl		cepted Pile of Stones
	1946-1957	Survey Notes	Williams & Work	s Found and Ac	cepted Intersection of Fences
	1980	L.C.R.C. #1390	Exxel Engineeri	ng Set Capped In	on at Int. of the 1/4 Lines

- В. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Found capped iron 4-5' West of fence corner running N-S, E & W per L.C.R.C. #1390 as set by Exxel Engineering at the intersection of 1/4 line. This point could be 4.5' M/L West of the Center Section as shown in 1904 Williams & Works notes and Williams & Works surveys 1904-1957 which noted the fence corner. Capped iron is 0.2' North and 0.1' East of the intersection of 1/4 lines. Accepted iron as the Center Section.

L.C.R.C. #1390

Nail in E side 10" Ash North 21.25' Nail in N side 24" Ash N 85° E 15.89'

P.A. 345 1990 KENT COUNT PEER APPROVED

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: E OF MICHIO
- Replaced the Capped Iron with a Standard 4" x 30" Kent County Monument

Nail & K.C. remon. tag in W side 12" Ash South 31.98'

Nail & K.C. remon, tag in W side 8" Elm North 4.79'

Nail & K.C. remon. tag in E side 10" Ash N 21.25'

Nail & K.C. remon. tag in N side 24" Ash N 85° E 15.98'

Fence corner East 4.5'

Signed by_

RANDY J. KOLEHOUSE LAND No. ENSED LAND SURVE

Surveyor's Michigan License No.