JAN 2 3 1996

LAND CORNER RECORDATION CERTIFICATE

COMMISSION	Filing Requirement of Act 74, Mich. P.A. 197
ACANADIAN CAMPACATA	KENT COUNTY REMONUMENTATION

For	corners in	A A SANGRAM	KEN-	T COUNTY REM	IONUMENTATION					
	Kent (Co	unty)	Located in:	Corner	Code #		R	95 OCT	STAT COU	
1.	Public Land	d Survey	T_5N R_12V	<u> </u>	4		6.0	<u> </u>	と同じ	
	• •		T R T R	<u>. </u>			TECO	Ē		
2.	Property Co	ontrolling S_	T	1			8739	9: 02		
3.	Miscellane) — S		- 400			0 602	LO	O	
•	Property in		TR			Register of D	eeds Stamp	& File N	Vumber	
4.	Lot No	, Record	ded Plat	·		_				
5.	Private Clai	ms	······································			A B	DEF	G H	ı J K	L
				. •		2 6 -	5 4	3-	2	- -
i, Randy Kolehouse, in a field survey on April 21 19 95, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points						4	 	10-		12-
do 1	tioned in line	y that under requir	ements of P.A. 74 Mid	chigan P.A. of 1	1970, the corner points	5			1-1-1-	1
in th	mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of						17 16		14	 13—
Lanc	l Managemer	nt or by a decree of :	a Court of Law and/or th	nat the comer poin	ats mentioned in lines 3	7				_
4 an	d 5 above w	ere in conformance	with the rules of the Mi	ichidan Board of	Land Surveyors or by a	819	20-21-	22	23-	24-
Decr	Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:									Ī
						10				Ţ
NOT			, all in the same town	ı and range, ma	y be recorded	11	1		100	/
	on thi	s certificate.		•						
A.	Description	on of original mone	ıment and accessorie	s:and/or subse	quent restoration:	12 31	32 33	34—	35	36
J-4	This corne	er was not originally	set by the G.L.O.	:		÷				
	NA	Wit. Map	K.C. S	urveyor	lron					
	1975	L.C.R.C. #896	10	Engineering	Set 3/4" Capped	Iron				
	1993	L.C.R.C. #678		vlarschall	Found and Accep		n which Fits			

- В. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Found standard Kent County Monument on line of fences running East and South per L.C.R.C. #6780A as set by C. Marschall in place of an Exxel capped iron they found to fit the 1/4 line intersection. K.C. Monument is 0.15' North of intersection of 1/4 (note: Also found iron 0.48' West). Accepted Kent County Monument as Center Section.

L.C.R.C. #6780A

Nail & Tag in SW side 24" Maple S 44° E 166.65' Nail & Tag in S side 8" Elm N 66° E 5.94' Nail & Tag in NW corner fence post RR tie S 15° W 6.55' Nail & Tag in E side 10" W. Cherry S 42° W 32.58'

P.A. 345 1990 KENT COUNT

- Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- Standard Kent County Monument

Nail & K.C. remon. tag in SW side 24" Maple S 44° E 166.65'

Nail & K.C. remon, tag in S side 8" Elm N 66° E 5.94"

Nail & K.C. remon, tag in NW corner RR tie fence post S 15° W 6,55'

25854

Nail & K.C. remon. tag in E side 10" W. Cherry S 42° W 32.58'

EARTH TECH Surveyor's Michigan License No.

1/4 Line Int./Set K.C. Monument

KOLEHOUSE

REVISED JAN., 1983