

**SURVEY &
REMONUMENTATION**

MAR 03 1998

SECTION

KENT COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

other code #4

For corners in
KENT COUNTY

Located In:

Corner Code #

1. Public Land Survey

T___ R___
T___ R___
T___ R___
T___ R___

2. Property Controlling
in Section

S 22 T 6N R 9W
S___ T___ R___

3. Miscellaneous
Property in Sec.

S___ T___ R___
S___ T___ R___

Wit. Mon. on
E-W 1/4 line

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Kirk Breitels, in a field survey on Aug. 18, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Not Set by GLO

See LCRC # 10277 for Central 1/4 corner (H-8) of Sec. 22

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Established East 1/8 corner on E-W 1/4 line of Sec. 22. Location falls in the C/L ± of a N-S gravel field drive. Fence line to West extended East is 3' ± North of this location.

The 1/8 corner as described above is accepted by me and is generally accepted by professional surveyors as the best available evidence of the witness corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Harrison Monument with witness cap at 1/8 corner described above.

Capped Rerod - traverse point

Nail & KC Remon. tag S. side 10" Maple

Nail & KC Remon. tag S. side 10" Beech

Nail & KC Remon. tag SE side 6" Elm

N05°E 91.92'

N90°W 58.11'

S75°W 59.01'

S40°W 49.75'

P.A.

PE

C

990 KENT COUNTY

PROVED 8/28/97

MAN [Signature]

Signed by

[Signature]

30077

Surveyor's Michigan License No. _____

Date

10/30/97

