FEB 1 4 1997

KENT COUNTY REMONUMENTATION

00	ħA) Å	MA	€ 6	4	9	18
2. 22. 3	264	9711	6	Sec. 3.	. 4.	Sec. 2.	1 4.5

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970											
For corners in KENT COUNTY	Located In:	Corn	er Code #		•						
(County)					her co	1 th/					
		l .		,,		, de 0					
 Public Land Survey 	T F	·		+0 "	her co						
	T F	·		O /	;						
	T F										
	21 7 6N F	10W Wit.	Mon. on			•					
Property Controlling Property Controlling	S 21 T 6N F		ine Sec. 21								
in Section 3. Miscellaneous	S F	\		` (9384						
Property in Section	S T F			Register of	Deeds Stamp & F	ile Number					
1 10,5010, 00040		·	:								
4. Lot No,	Recorded Plat	<u> </u>		A (3 C D E F G	.H I J K					
5. Private Claims		1									
C _Z	. 1			2		3 - 2					
				3							
Kirk Breitels		Sept. 18	19 96	4	8-1-9-1-	10-11-1					
do hereby certify that under re	, in a field survey on equirements of P.A. 74. Micl			ioned							
in lines 1 and 2 above were in	conformance with regulatio	ns and rules therefore	as required in the cu	urrent	3-17-16-1-	15-14-1-1					
manual of survey instructio											
Management or by a decree 5 above were in conformance					20 21	2223					
Decree of a Court of Law; es				found							
as expressed below:				10 -30)2928	27 26 2					
NOTE: Not more than 4 c	orners, all in the same to	wn and range, may	be recorded	11							
on this certificate.				12 -31	32 33	34353					
A. Description of origina	I monument and access	ories and/or subse	quent restoration	:	, vo						
•	45 H		.		27 0	8					
1831 GLO	Not Set					EST -					
		- !	- "	ć	3 / _	自善而 !					
				5	500 °°	글근목					
	. 1	•				医光泽					
4		!		, in		到過美					
						3 H 2					
					9	5 **					
B. Description of corner Set Standard Ken	evidence found and/or i	method applied in r	estoring or reesta	ablishing corner:	ba O/L Oandu	- a d					
Dr. the N. line	of Sec. 21 as es	ument on the nar	1 CRC #3707	ec. Zi aliq t	ne c/L Goodwa	50 u					
	J. 000. 2. 40 00	tablifolica por	1010								
			! !								
The selected loc	ation is accepte	d by me and	is generall	y accepted l	oy profession	nal					
surveyors as the	best available l	ocation of the	e corner.		i,						
			-			-					
		f			•						
•		:									
C. Description of monun	ant for corner and acce	centiae actablished	to perpetuate la	nating the positio	n of the corner						
Standard Kent Co.			io perpendie loi	camy me posido	n or the comer:						
NE corner of bi	1 .1	· ,	\$55°W 41	1.75	100000000000000000000000000000000000000						
	Remon. tag S. side	e Tw. 24" Oak	30 1	0.02'	BF MICH						
Set Nail & KC F	Remon. tag E. side	P. Pole	Pl 1	3.35'		74 X					
	Remon. tag S. side	e Tw. 30" Oak	101).51' 🔏	KIRK BREITELS	A # 18					
NW corner of br	ick sign		₹* _	.10	LAND	7 1					
C/L Manhole	on of NE pornor	; sf 800 01	at !	7.08	SURVEYOR	1 8					
Concrete Monume	on of NE corner o	or sec. 21	E1 1 .	3.15' % '	No.	138					
CONTRACTOR MORITIME			Last 33		30077						
//		:		,*	(4HB 38						

Signed by Surveyor's Michigan License No.

RVEYORS, JAN. 28, 197 REVISED MAY 14, 197 REVISED JAN., 198

P.A. 345 1990 KENT COUNTY PEER APPROVED 9/26